

U.S. Department of Transportation

National Highway Traffic Safety Administration

November 24, 2021

Mr. Jeff Chang
Honda (American Honda Motor Co.)
1919 Torrance Blvd
Torrance, CA 90501

NEF-107JK
21V-901

Subject: Insufficient Fuel May Cause Stall

Dear Mr. Chang:

This letter serves to acknowledge Honda (American Honda Motor Co.)'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

1200 New Jersey Avenue SE Washington, DC 20590

Makes/Models/Model Years:

HONDA/NC750XD/2021

Mfr's Report Date: November 18, 2021

NHTSA Campaign Number: 21V-901

Components:

FUEL SYSTEM, GASOLINE: FUEL INJECTION SYSTEM

Potential Number of Units Affected: 357

Problem Description:

Honda (American Honda Motor Co.) is recalling certain 2021 NC750XD motorcycles equipped with 6-speed dual clutch automatic transmissions. The fuel injection control module software may be programmed incorrectly, which can result in insufficient fuel when stopping, or accelerating from a stop.

Consequence:

Insufficient fuel can cause a stall, increasing the risk of a crash or injury.

Remedy:

Dealers will reprogram the fuel injection and dual clutch transmission software, free of charge. Owner notification letters are expected to be mailed January 7, 2022. Owners may contact Honda Powersports customer service at 866-784-1870. Honda's number for this recall is KN0.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Honda (American Honda Motor Co.)'s contact for this recall will be Jennifer Kruger who may be reached by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

