

Subject:

Model Y Suspension Knuckle Inspection



Tesla has decided to proactively recall certain Model Y vehicles to inspect their suspension knuckles. This recall applies to certain Model Y vehicles built between June 2020 and November 2021. Our records indicate that your vehicle, <VIN>, may be affected by this recall.

On these vehicles, the front and/or rear suspension knuckles may not meet the correct manufacturing specifications, which may allow the knuckle to deform or fracture and possibly separate from the suspension links. If the suspension links separate from the knuckle, the wheel alignment could shift, which may impact vehicle controllability. In such cases, you may detect abnormal noise or handling.

We are not aware of any crashes or injuries relating to this condition.

No immediate action is required if you own a Model Y affected by this recall, and you may continue to drive your car. Tesla will contact you to schedule a service appointment when tools become available in your region to inspect your suspension knuckles and replace if needed, free of charge.

Thank you for being a Tesla customer, and we apologize for this inconvenience.