

[Next Unread Message](#)[View Message](#)

Sent on	12	01	2021	Expires on	12	20	2021
----------------	----	----	------	-------------------	----	----	------

From	Parts Division
-------------	----------------

Subject	Hood Repair Kit 06601-TG7-305: 16-19M Pilot, 17-20M Ridgeline, 19M Passport Hood
----------------	--

On November 30, 2021, American Honda announced a Safety Recall for certain 16-19M Pilot, 17-20M Ridgeline, 19M Passport vehicles. This Safety Recall is for vehicles that have improperly adjusted front hoods. Under certain conditions, the hood may open while driving, increasing the risk of a crash.

Demand on the Rivet Kits (06601-TG7-305) used in inspection process B noted in Service Bulletin 21-086 Safety Recall: Hood Vibration at Highway Speeds has been much higher than anticipated. This Rivet kit repair is required in limited cases based on inspection of the hood. American Honda is working with our supplier to make additional parts available. To allow for as many repairs as possible, effective immediately, December 1st, parts are no longer available for open dealer ordering.

American Honda is continuing to work with our supplier and we hope to have this situation resolved by early in 2022. **After completed inspection**, if Rivet Kit 06601-TG7-305 is required for repair, please contact your local dealer analyst (844-510-7778) or DPSM and provide VIN number so the part can be ordered/shipped. Additional details and information will be shared as it becomes available.

Thank you,

American Honda Motor Co., Inc.