

Recall Quarterly Report

21V-954

Manufacturer Name : Subaru of America, Inc.
NHTSA Recall No. / MFR Recall No. : 21V-954 / WRL-21
Recall Subject : Tie Rods May Separate
Owner Notification Beginning Date : FEB 07, 2022
Owner Notification End Date: FEB 07, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JUL 25, 2022	2022-2	1,305	791	0	2
1	APR 27, 2022	2022-1	1,305	480	0	2

This Document Last Updated : JUL 28, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.