

**Recall Quarterly Report****21V-954****Manufacturer Name :** Subaru of America, Inc.**NHTSA Recall No. / MFR Recall No. :** 21V-954 /WRL-21**Recall Subject :** Tie Rods May Separate**Owner Notification Beginning Date :** FEB 07, 2022**Owner Notification End Date:** FEB 07, 2022

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	OCT 21, 2022	2022-3	1,305	971	0	4
2	JUL 25, 2022	2022-2	1,305	791	0	2
1	APR 27, 2022	2022-1	1,305	480	0	2

This Document Last Updated : OCT 26, 2022

**Definitions :**Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.