

Recall Quarterly Report

21V-963

Manufacturer Name : Southeast Toyota Distributors, LLC
NHTSA Recall No. / MFR Recall No. : 21V-963 / SET21A
Recall Subject : Inoperable Driver's Side High Beam/FMVSS 108
Owner Notification Beginning Date : FEB 11, 2022
Owner Notification End Date: FEB 11, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 20, 2022	2022-1	78	18	1	0

This Document Last Updated : APR 21, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
Recall Population : The total number of products recalled by the manufacturer.
Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.
Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.
Total Removed : Products that have been scrapped, stolen, or exported.