

# Part 573 Safety Recall Report

# 21V-984

**Manufacturer Name :** Bugatti**Submission Date :** DEC 16, 2021**NHTSA Recall No. :** 21V-984**Manufacturer Recall No. :** BUGCR025**Manufacturer Information :**

Manufacturer Name : Bugatti

Address : 1 Chateau St Jean  
Dorlisheim, France 00 67120

Company phone : 999

**Population :**

Number of potentially involved : 9

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2021-2022 Bugatti Chiron Pur Sport

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

**Descriptive Information :** The recall population from was determined by looking at the prototype vehicles equipped with the same tires as first production cars to currently produced vehicles. The number of affected vehicles overall is 9 within the United States. The vehicles affected are 2021-2022 Bugatti Chiron Pur Sport vehicles.

Production Dates : APR 27, 2020 - OCT 17, 2021

VIN Range 1 : Begin : VF9SC3V31MM795008 End : VF9SC3V35NM795031  Not sequential**Description of Defect :**

**Description of the Defect :** On one prototype vehicle, some cracks have been observed on rear specific Pur sport tires. During all drives no tire pressure drop have been observed. All Pur sport model vehicle have the same rear tires. All production tires made for the Bugatti PurSport are impacted starting with the pre-series tires in DOT1920 Rear tires for the 22 vehicles on the market accounts to 44 tires impacted

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** Rapid loss of tire pressure could lead to loosing the car control

**Description of the Cause :** Supplier is currently not able to asse the root cause of the cracks. The propagation of such cracks are not known but only observed above 4000km. Supplier during analysis could assure that any tire having less than 2500 miles and 2 years (DOT) wouldn't have any propagated cracks.

**Identification of Any Warning that can Occur :** Tire pressure monitoring system warning light in dashboard instrument cluster

## Involved Components :

Component Name 1 : Michelin CUP2R

Component Description : Tire

Component Part Number : 355/25ZR21

## Supplier Identification :

### Component Manufacturer

Name : Michelin

Address : 63040 Clermont-Ferrand

Places des Carmes Foreign States Cedex 9 Fr

Country : France

## Chronology :

On one prototype vehicle, some cracks have been observed on rear specific Pur sport tires. During all drives no tire pressure drop have been observed. All Pur sport model vehicle have the same rear tires.

## Description of Remedy :

Description of Remedy Program : All Pur sport vehicle delivered will get new rear tires that are less than 2 years and 0 miles. After the replacement, the customer will be instructed to replace the tires before reaching the 1875 miles or 1,5 years. Supplier is working on a new rear tires that will take into account the results of the current root cause analysis ongoing. When these tires will be available, all Pur sport car will get a set of tires. All rear tires replacement will be covered by Bugatti until the new specification set of rear tires will be mounted. Transport of the car for the first tire replacement will be also covered

How Remedy Component Differs from Recalled Component : There are no physical differences between the remedy component and the recalled component. The remedy component will have the reduced risk of the cracks appearing by replacing them at a reduced mileage and time limit until a the source of the cracks are identified and a permanent solution identified.

Identify How/When Recall Condition was Corrected in Production : The recall condition has not been corrected in production as of yet until the source of the concern is determined.

**Recall Schedule :**

Description of Recall Schedule : We would like the approval from NHTSA prior to sending out the recall notices. We're anticipating beginning of notification by January 1, 2022

Planned Dealer Notification Date : JAN 01, 2022 - FEB 16, 2022

Planned Owner Notification Date : JAN 01, 2022 - JAN 01, 2022

\* NR - Not Reported