

# Part 573 Safety Recall Report

## 22C-007

**Manufacturer Name :** JD E-Commerce America Limited

**Submission Date :** DEC 13, 2022

**NHTSA Recall No. :** 22C-007

**Manufacturer Recall No. :** NR



### Manufacturer Information :

**Manufacturer Name :** JD E-Commerce America Limited

**Address :** 19900 Macarthur Blvd  
Suite 660 Irvine CA 92612

**Company phone :** 946-932-0299

### Population :

**Number of potentially involved :** NR

**Estimated percentage with defect :** NR

### Child Restraint Information :

**Make 1 :** Marainbow

**Model :** Portable Infant Safe Seat

**Seat Type :**

**Model No. :** N/A

**Platform Name / No. :** NR

**Brand Name :** NR

**Descriptive Information :** The recall population was determined following discussions with NHTSA staff and a review of internal sales records. All Marainbow Portable Infant Safe Seats, as well as materially similar products which may suffer from the noted defects, are included in the recall. The number of products included in the recall is 174.

**Production Dates :** AUG 02, 2020 - MAY 07, 2022

### Description of Noncompliance :

**Description of the Noncompliance :** According to a letter dated December 1, 2020, NHTSA determined that the Marainbow Portable Infant Safe Seat child restraint system contains deficiencies [] which constitute possible noncompliance with FMVSS No. 213: S5.3.1(a), S5.3.2, S5.5. S5.6. S5.8, S5.9, and failure to file in accordance with 49 C.F.R. Part 566 and 49 C.F.R. Part 551."

**FMVSS 1 :** 213 - Child restraint systems

**FMVSS 2 :** NR

**Description of the Safety Risk :** The noted noncompliance does not affect the dynamic performance of the child restraint but the products may not have the required labeling as specified in S5.5, printed instructions as required by S5.6 or the product registration card as required by S5.8. The failure to provide the required information could result in caregivers using the CRS inappropriately and the failure to provide a mechanism for customers to register the CRS with a

manufacturer increases the difficulty of locating customers in the event of a recall.

Further, these child restraint systems were designed to be attached to the back and/or cushion which fails the requirements listed in S5.3.1 (a). The CRS also lacks the ability to be installed using the methods required by S5.3.2 & S5.9 for a CRS of this type. Failure to comply with these safety standards may result in improper installation and increase the risk of injury.

Description of the Cause : NR

Identification of Any Warning NR  
that can Occur :

### Involved Components :

Component Name : NR

Component Description : NR

Component Part Number : NR

### Supplier Identification :

#### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

### Chronology :

NR

### Description of Remedy :

Description of Remedy Program : Please contact 1-302-426-4543 for more information about the recall. To receive a refund, you must send visual proof of the destruction of the car seat, such as photographs or a short video, to the following email [overseaservice@jd.com](mailto:overseaservice@jd.com).

How Remedy Component Differs NR  
from Recalled Component :

Identify How/When Recall Condition NR  
was Corrected in Production :

### Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

### Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

\* NR - Not Reported