

Part 573 Safety Recall Report

22E-004

Manufacturer Name : Prevost Car (US) Inc.

Submission Date : MAY 10, 2023

NHTSA Recall No. : 22E-004

Manufacturer Recall No. : ER22-14



Manufacturer Information :

Manufacturer Name : Prevost Car (US) Inc.

Address : 201 South Avenue
South Plains NJ 07080

Company phone : 908-222-7211

Population :

Number of potentially involved : 72

Estimated percentage with defect : 100 %

Equipment Information :

Brand / Trade 1 : Non applicable

Model : Non applicable

Part No. : 860351 & 860355

Size : NR

Function : Seat bracket

Descriptive Information : Seat bracket, which is a single structure component, designed for entertainer vehicles were manufactured based on a defective drawing. The final product did not fulfilled the strength requirements.

Vehicles affected for this P/N issue are entertainers equipped with passenger seatbelts anchored to the seat. (Shell vehicles) MY2020 to MY2022.

Production Dates : JAN 01, 2020 - JAN 01, 2022

Description of Defect :

Description of the Defect : Seat bracket for entertainer vehicles are not strong enough to support design mechanical loads

FMVSS 1 : 210 - Seat belt assembly anchorages

FMVSS 2 : NR

Description of the Safety Risk : Potential injury of passengers in case of crash.

Prevost has not received a report of death or injury associated with this defect. Therefore we consider this as a proactive measure to protect the public from the potential risk associated with this defect.

Description of the Cause : Design related defect

Identification of Any Warning that can Occur : Non applicable

Involved Components :

Component Name : Seat bracket

Component Description : 0.1" thick steel sheet cut and welded 1.5" x 1.5" x 6"

Component Part Number : 860351 & 860355

Supplier Identification :**Component Manufacturer**

Name : Prevost Car (US) inc.

Address : 7900 National Service Rd.
Greensboro North Carolina 27409

Country : United States

Chronology :

- 2021-12-22: Issue was reported to Product Safety Manager
- 2022-01-11: Case submitted for investigation to Product Safety Working Group (PSWG) as a potential safety related issue
- 2022-01-18: Case raised to the Product Safety Committee (PSC). PSC determines that a safety defect exists.

Description of Remedy :

Description of Remedy Program : A safety recall will be released to replace the defective brackets with new reinforced brackets compliant with the design loads. Owner letters will be mailed on or before March 21st, 2022.

How Remedy Component Differs from Recalled Component : New brackets will look the same as old brackets but, they will have an additional welding; P/N 860351 is replaced by P/N 868187 and P/N 860355 is replaced by P/N 868188

Identify How/When Recall Condition was Corrected in Production : Bracket drawing was updated to show the missing welding and was released for production. P/N 860351 is replaced by P/N 868187 and P/N 860355 is replaced by P/N 868188

Recall Schedule :

Description of Recall Schedule : Note Prevost does not have a dealer network and the dates entered for

the planned dealer notification begin/end date are only to avoid NHTSA Recall Portal error while submitting the recall report.

Notification Letters were sent to customers on March 15th 2022

Planned Dealer Notification Date : MAR 21, 2022 - MAR 21, 2022

Planned Owner Notification Date : MAR 21, 2022 - MAR 21, 2022

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : ALL ACCESS COACH LEASING, LLC

Address : 364 NORTH WATER AVE
GALLATIN TN 37066

Country : US

Company Phone : 6152307400

Name : D & S CLASSIC COACH RENTALS, INC.

Address : 23910 NORTH 19TH AVENUE STE 60
PHOENIX AZ 85085

Country : US

Company Phone : 6235809190

Name : ESSEX COACH, INC.

Address : 2134 LONG HOLLOW PIKE
GALLATIN TN 37066

Country : US

Company Phone : 6158247303

Name : FLORIDA COACH, INC

Address : 3150 FLORIDA COACH DRIVE
KISSIMMEE FL 34741

Country : US

Company Phone : 4078462782

Name : INTEGRITY INTERIORS LLC

Address : 2951 Union Rd
WHITE HOUSE TN 37188

Country : US

Company Phone : 6156725896

Name : JIMMY HOLMES

Address : 2134 LONG HOLLOW PIKE
GALLATIN TN 37066

Country : US

Company Phone : 6156180408

Name : NASHVILLE COACH INC.

Address : 234 MOLLY WALTON DRIVE
HENDERSONVILLE TN 37075

Country : US

Company Phone : 6154252410

Name : OUTLAW CONVERSIONS, INC.

Address : 1000 Airport Rd
STEPHENVILLE TX 76401

Country : US

Company Phone : 2549685733

Name : PIONEER COACH INTERIORS LLC

Address : 805 MADISON INDUSTRIAL BLVD
MADISON TN 37115

Country : US

Company Phone : 6158601690

Name : PIONEER COACH, INC

Address : 805 MADISON INDUSTRIAL BLVD
MADISON TN 37115

Country : US

Company Phone : 6158601690

Name : ROBERTS BROTHERS COACH LEASING CO.

Address : 1330 GATEWAY DRIVE
GALLATIN TN 37066

Country : US

Company Phone : 6152120226

Name : ROBERTS BROTHERS COACH CO., INC.

Address : 1330 GATEWAY DRIVE
GALLATIN TN 37066

Country : US

Company Phone : 6152120226

* NR - Not Reported