## **Recall Quarterly Report**

22E-036

Manufacturer Name : Performance Machine, Inc. NHTSA Recall No. / MFR Recall No. : 22E-036 / Recall Subject : Weld May Crack Causing Handlebar Separation Owner Notification Beginning Date : JUN 29, 2022 Owner Notification End Date: JUN 29, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	NOV 01, 2022	2022-3	910	326	4	0
1	OCT 21, 2022	2022-2	910	312	4	0

This Document Last Updated : NOV 02, 2022

## **Definitions** :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.

The information contained in this report was submitted pursuant to 49 CFR §573.7