OMB Control No.: 2127-0004

Recall Quarterly Report

22E-059

Manufacturer Name: Besser Pro, LLC

NHTSA Recall No. / MFR Recall No.: 22E-059 / Recall Subject: Axle May Crack and Separate

Owner Notification Beginning Date : AUG 01, 2022

Owner Notification End Date: AUG 01, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	APR 30, 2023	2023-1	803	1	0	802
2	JAN 30, 2023	2022-4	803	1	0	802
1	OCT 31, 2022	2022-3	803	0	0	802

This Document Last Updated: MAY 02, 2023

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.