

Recall Quarterly Report**22E-059**

Manufacturer Name : Besser Pro, LLC
NHTSA Recall No. / MFR Recall No. : 22E-059 /
Recall Subject : Axle May Crack and Separate
Owner Notification Beginning Date : AUG 01, 2022
Owner Notification End Date: AUG 01, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JAN 30, 2023	2022-4	803	1	0	802
1	OCT 31, 2022	2022-3	803	0	0	802

This Document Last Updated : JAN 31, 2023

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.