

TOYOTA MOTOR  
NORTH AMERICA

Quality

Toyota Motor Sales, USA, Inc.  
6565 Headquarters Drive  
Plano, TX 75024  
(469) 292-4000

Original Publication Date: December 21, 2023

To: All Toyota Dealer Principals, General Managers, Service Managers, and Parts Managers

## EQUIPMENT SAFETY RECALL 22TH01

### Defective Seatbelt Retractor Force Limiter NHTSA Recall No. 22E-095

*On November 10, 2022, Toyota filed an Equipment Safety Recall regarding certain front seat belt service parts distributed to Toyota dealers. Certain Highlander vehicles have been identified that could potentially have defective seatbelts installed. These vehicles are now included in Equipment Safety Recall 22TH01.*

- A component in the subject front seat belt assemblies may not have been manufactured properly and may cause the seat belt to not operate as designed. This can increase the risk of an injury in the event of certain types of crashes.
- Any authorized Toyota dealer will inspect the seat belt assembly and, if necessary, replace it FREE OF CHARGE.
- Equipment Safety Recall 22TH01 Dealer Letter and Technical Instructions now available on TIS.

**Refer to the Dealer Letter and Technical Instructions on TIS for additional information.**

Thank you for your cooperation.  
TOYOTA MOTOR SALES, U.S.A., INC.