

# Part 573 Safety Recall Report

## 22E-096

**Manufacturer Name :** ScentLok Technologies

**Submission Date :** NOV 22, 2022

**NHTSA Recall No. :** 22E-096

**Manufacturer Recall No. :** 82913 and 4150390



### Manufacturer Information :

**Manufacturer Name :** ScentLok Technologies

**Address :** 1731 Wierengo Drive

Muskegon MI 49442

**Company phone :** 6404063

### Population :

**Number of potentially involved :** 16,667

**Estimated percentage with defect :** NR

### Equipment Information :

**Brand / Trade 1 :** OZ

**Model :** OZ20

**Part No. :** 82913 and 4150390

**Size :** NR

**Function :** NR

**Descriptive Information :** Nexus Outdoors, Inc. is initiating a voluntary recall of the OZ20 Vehicle Deodorizer.

#### Reason for voluntary recall:

- Potential exists for the unit to overheat when in use, possibly resulting in melting or fire.
- No serious injuries or deaths have been reported.
- We are aware of 4 product failures related to this issue.

#### What to do next?

- We are asking all consumers to return all affected units. This recall only affects purchases with product numbers 82913 or 4150390 on the back side of the housing unit or on the UPC sticker located on the back of the original packaging.
- Contact [recall@nexus-outdoors.com](mailto:recall@nexus-outdoors.com) or call 231-220-1600 to receive a pre-paid shipping label to send your OZ20 unit back to us.
- Nexus Outdoors will ship you a replacement unit, free of charge.

**Number of units affected:** 16,667

**Retail price:** 34.99

**How does recalled product differ from product not included in recall:** internal componentry/connections have been updated.

**Where available:** [scentlok.com](http://scentlok.com) (notice is on website), various retailers (notice has been sent to all retailers)

**Production Dates :** JAN 01, 2018 - AUG 17, 2019

**Description of Defect :**

Description of the Defect : In certain instances, the OZ20 Vehicle Deodorizer can overheat, which may result in the unit melting and/or causing a fire hazard. Nexus Outdoors has reported no injuries or deaths have resulted from this product to date.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In certain instances, the OZ20 Vehicle Deodorizer can overheat, which may result in the unit melting and/or causing a fire hazard. Nexus Outdoors has reported no injuries or deaths have resulted from this product to date.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Involved Components :**

Component Name : OZ20

Component Description : OZ20 Vehicle Deodorizer

Component Part Number : 82913 and 4150390

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

Below is a summary of incidents that gave rise to management to initiate a recall for the OZ20 Vehicle Deodorizer. The latest 2022 cases the damaged has not yet been determined on two trucks with no damage on the third instance.

In no cases has there been any injuries and or deaths.

September 2022, 2002 Ford F-250 truck fire, extent of damage unknown

September 2022, 2011 Chevrolet Silverado truck fire, extent of damage unknown

September 2022, truck, burning smell, no damage

## Description of Remedy :

Description of Remedy Program : Reason for voluntary recall:

- Potential exists for the unit to overheat when in use, possibly resulting in melting or fire.
- No serious injuries or deaths have been reported.
- We are aware of 3 product failures related to this issue.

### What to do next?

- We are asking all consumers to return all affected units. This recall only affects purchases with product numbers 82913 or 4150390 on the back side of the housing unit or on the UPC sticker located on the back of the original packaging.
- Contact [recall@nexus-outdoors.com](mailto:recall@nexus-outdoors.com) or call 231-220-1600 to receive a pre-paid shipping label to send your OZ20 unit back to us.
- Nexus Outdoors will ship you a replacement unit, free of charge.

How Remedy Component Differs from Recalled Component : Remedy component = OZ20HD, item number 4151290  
Recalled component = OZ20, item numbers 82913 and 4150390

Identify How/When Recall Condition was Corrected in Production : Internal electronic connection updated.

## Recall Schedule :

Description of Recall Schedule : Recall notifications have been sent to all distribution channels. Copies of web alert, social media postings, press release, emails and letter to retail partners are available.

Planned Dealer Notification Date : NOV 17, 2022 - DEC 17, 2023

Planned Owner Notification Date : NOV 17, 2022 - NOV 17, 2022

## Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

\* NR - Not Reported