

Part 573 Safety Recall Report

22T-012

Manufacturer Name : Shandong New Continent Tire Co., Ltd.

Submission Date : SEP 08, 2022

NHTSA Recall No. : 22T-012

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Shandong New Continent Tire Co., Ltd.

Address : c/o Theodore A. Parker
625 Main Street #37 Reading MA
01867

Company phone : 0539-2655299

Population :

Number of potentially involved : 2,045

Estimated percentage with defect : 11 %

Tire Information :

Tire Brand 1 : Rolling Big Power

Tire Line : Repulsor M/T

Tire Size : 285/75R16LT

Descriptive Information : Some tires of this model and size may experience impermissible lower sidewall damage during endurance testing. No other sizes or models are affected.

Production Dates : APR 02, 2018 - APR 10, 2022

TIN (Tire Identification Number)

Plant ID	Size code	Optional Code	Begin M Code	End M Code
AJ	D6LCDE	NR	1418	1622

Description of Noncompliance :

Description of the Noncompliance : Some tires of this model and size experience impermissible lower sidewall damage during endurance testing.

FMVSS 1 : 139 - New pneumatic radial tires for light vehicles

FMVSS 2 : NR

Description of the Safety Risk : If sidewall separation occurs while a vehicle is being driven, the tire could suddenly lose pressure, causing a vehicle to lose control and possibly crash.

Description of the Cause : Some tires of this model and size were manufactured with a thickness at the RC-T point that was too thin to comply with the endurance testing requirements of FMVSS 139.

Identification of Any Warning that can Occur : The vehicle's Tire Pressure Monitoring System (TPMS) may detect a loss of pressure that could precede a sidewall separation.

Involved Components :

Component Name : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On or around June 22, 2022, the Company was notified by NHTSA that one of the subject tires had been deemed to have failed the endurance test requirement of FMVSS 139 Section 6.3.2(a) by showing signs of sidewall separation. The Company proceeded to investigate this allegation and submitted a Part 573 report on July 28, 2022. After further technical discussions with NHTSA, the Company has elected to recall all tires of this model and size that predate the submission of this updated Part 573 report.

Description of Remedy :

Description of Remedy Program : The Company will reimburse the total amount paid for the replacement tire(s) up to the retail price of the recalled tire(s), plus a fixed amount for installation and rotation.

How Remedy Component Differs from Recalled Component : The recalled tires will be replaced with FMVSS 139-compliant tires.

Identify How/When Recall Condition was Corrected in Production : The specifications of this model and size of tire are being redesigned.

Recall Schedule :

Description of Recall Schedule : This will be supplemented.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

* NR - Not Reported