

# Part 573 Safety Recall Report

# 22T-014

**Manufacturer Name :** PT. Elangperdana Tyre Industry

**Submission Date :** SEP 08, 2022

**NHTSA Recall No. :** 22T-014

**Manufacturer Recall No. :** Not applicable.



## Manufacturer Information :

## Population :

Manufacturer Name : PT. Elangperdana Tyre Industry

Number of potentially involved : 15,964

Address : Jl. Elang, Desa Sukahati, Citeureup  
Bogor West Java Bogor West Java 00  
16810

Estimated percentage with defect : 100 %

Company phone : 999

## Tire Information :

Tire Brand 1 : Zeetex AT 1000

Tire Line : Light Truck

Tire Size : LT245/75R17

Descriptive Information : The entire population of Zeetex AT 1000 size LT 245/75R17 imported into the U. S.

Production Dates : NOV 02, 2014 - JUN 12, 2022

### TIN (Tire Identification Number)

Plant ID	Size code	Optional Code	Begin M Code	End M Code
109	45/75R17	NR	7842	7842

Tire Brand 2 : Zeetex AT1000

Tire Line : Light Truck

Tire Size : LT235/80R17

Descriptive Information : NHTSA letter dated June 22, 2022.

Production Dates : FEB 09, 2019 - JUN 22, 2022

### TIN (Tire Identification Number)

Plant ID	Size code	Optional Code	Begin M Code	End M Code
109	1J51 50	NR	0619	2522

Tire Brand 3 : Zeetex AT 1000

Tire Line : Light truck

Tire Size : LT275/70 R18

Descriptive Information : A letter from NHTSA dated June 22, 2022. Internal test result. 2789.

Production Dates : MAR 25, 2019 - JUN 22, 2022

### TIN (Tire Identification Number)

Plant ID	Size code	Optional Code	Begin M Code	End M Code
109	1F61 50	NR	1319	2522

Tire Brand 4 : Zeetex AT1000

Tire Line : Light truck

Tire Size : LT285/75 R16

Descriptive Information : A letter from NHTSA. Internal testing of products.

Production Dates : JAN 22, 2017 - JUN 22, 2022

### TIN (Tire Identification Number)

Plant ID	Size code	Optional Code	Begin M Code	End M Code
109	2A81 50	NR	0417	2522

Tire Brand 5 : Zeetex AT1000

Tire Line : Light truck

Tire Size : LT275/65 R20

Descriptive Information : A letter from NHTSA dated June 22, 2022. Internal testing. 15,964

Production Dates : MAY 17, 2020 - JUN 22, 2022

### TIN (Tire Identification Number)

Plant ID	Size code	Optional Code	Begin M Code	End M Code
109	2A81 50	NR	2020	2522

### Description of Defect :

Description of the Defect : Premature sidewall separation near the bead area

FMVSS 1 : 139 - New pneumatic radial tires for light vehicles

FMVSS 2 : NR

Description of the Safety Risk : Premature failure of the subject tire which may cause personal injury, property damage or even death.

Description of the Cause : Under investigation

Identification of Any Warning that can Occur : Unusual vibration of the vehicle or noise.

## Involved Components :

Component Name : Not applicable

Component Description : NR

Component Part Number : NR

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

Receipt of a letter dated June 22, 2022 from NHTSA stating its compliance test revealed sidewall separation near the bead area.

## Description of Remedy :

Description of Remedy Program : Recall for monetary compensation

How Remedy Component Differs from Recalled Component : Not applicable

Identify How/When Recall Condition was Corrected in Production : It has not yet been corrected but production has stopped.

## Recall Schedule :

Description of Recall Schedule : As soon as possible.

Planned Dealer Notification Date : AUG 31, 2022 - OCT 31, 2022

Planned Owner Notification Date : AUG 31, 2022 - OCT 31, 2022

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

\* NR - Not Reported