

IMPORTANT SAFETY RECALL

RECALL NO. 22T-017

October 2022

Dear Valued Falken Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Sumitomo Rubber USA, LLC (SRUSA) has decided that a defect which relates to motor vehicle safety exists in certain Falken brand Pro G5 CSV passenger-car tires manufactured between February 28, 2022 and March 5, 2022. Suspect tires contain inadequate sulfur levels in the treadbase compound, which prevented proper curing of the tread-base rubber. SRUSA has initiated a safety recall for the tires detailed in the attached list of affected tires (the affected-tire list).

We are notifying you because our records indicate that you may have purchased a tire(s) subject to this recall. Therefore, please review this letter carefully.

What is the Problem?

The tread may chunk or separate from the tire. (See the following photograph for an example.) If the tread chunking or separation occurs in a manner that affects vehicle stability, there may be an increased risk of a crash.







What Are We Doing About the Problem?

Consistent with the company's longstanding commitment to safety, customer satisfaction and service, SRUSA will replace tires subject to the recall with new tires, and mount the replacement tires, all at no charge to you through **April 18, 2023**. Any tire subject to this recall will be replaced with a comparable Falken tire. In the event that a Falken brand tire is not currently available, a suitable competitive product may be used as a replacement.

How Do You Identify Recalled Tires?

Tires have certain unique sidewall markings that will allow you to determine whether they are subject to this recall. The attached affected-tire list describes the **tire brand, tire line, tire size, and tire identification number (circled in red)** for each of the tires subject to this recall. Any tire that has **all four markings** described in the attached affected-tires list is subject to this recall and should be replaced.



SUMITOMO RUBBER USA, LLC



The tire identification number (TIN) can be found on the sidewall, as shown below. The TIN starts with the letters "DOT" with the last four numbers being the week and year manufactured, as shown circled in red below.



How To Have Your Tires Replaced

If any of your tires contain all four of the above-described sidewall markings, please immediately contact:

SRNA Employees	Please Contact: Tim Widener Sr. Manager, Tech. Service & Quality Assurance Sumitomo Rubber North America, Inc. Twidener@srnatire.com (909) 694-3151					
SRUSA Employees	Please Contact: Michael S. Wells Quality Assurance Manager Sumitomo Rubber USA, LLC. michael wells@sumitomorubber-usa.com (716) 879-8511					

The above contacts will confirm the tire is covered by the recall by inspection and will arrange to replace your tires at our expenses with no cost to you.

Questions or Concerns?

If you have questions or concerns about this recall, please contact either Tim Widener or Michael Wells

If you believe that SRUSA or has failed or is unable to provide a remedy without charge within a reasonable time, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

We are taking this action in the interest of your safety and satisfaction with our products. We apologize for any inconvenience and thank you for your attention to this matter.

Sincerely,	
Sumitomo Rubber USA, LLC.	
Enclosure	





Attachment: Affected tire list.

				13 Digit Tire Identification Number (TIN)			
FTC#	DTC#	Brand	Tire Line & Size	Plant ID	Size Code	Opt Code	DOT Week
28658085	37726	Falken	235/65 R17 104V Pro G5 CSV	1DA	L8	4MCR	0922
28658603	37721	Falken	235/65 R18 106V Pro G5 CSV	1DA	VK	4MCR	0922
28658591	37728	Falken	245/50 R20 102V Pro G5 CSV	1DA	KH	4MCR	0922
28653367	37743	Falken	265/50 R20 111V Pro G5 CSV	1DA	7E	4MCR	0922