

Part 573 Safety Recall Report

22V-002

Manufacturer Name : LGS Industries, Inc.**Submission Date :** JAN 04, 2022**NHTSA Recall No. :** 22V-002**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : LGS Industries, Inc.

Number of potentially involved : 9

Address : PO Box 339

Estimated percentage with defect : 100 %

BRISTOL IN 46507-0339

Company phone : 574-848-5665

Vehicle Information :

Vehicle 1 : 2014-2021 LGS Industries Cargo Sport, Shadow, Journey, Premier Race, Aftershock.

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : LGS has heard about two incidents occurring on competitors' box trailers where the winch cable securing the rear door snapped, causing the rear door to freefall and strike bystanders. LGS has not received reports of any winch cables snapping, or of any similar incidents on its box trailers, and believes its trailers were properly designed and manufactured, and meet all applicable FMVSS. Nonetheless, in an abundance of caution, LGS has decided to field modify the 9 units it has sold since 2014 on which a snapped winch cable could cause the rear door to freefall and injure a bystander. These are units equipped with a winch cable as the sole means of securing the rear door.

Production Dates : JAN 01, 2014 - OCT 31, 2021

VIN Range 1 : Begin : 53BPTEC31GA023091 End : 53BAGEE36MB006901 ☒ Not sequential**Description of Defect :**

Description of the Defect : LGS has heard about two incidents occurring on competitors' box trailers where the winch cable securing the rear door snapped, causing the rear door to freefall and strike bystanders. LGS has not received reports of any winch cables snapping, or of any similar incidents on its box trailers, and believes its trailers were properly designed and manufactured, and meet all applicable FMVSS. Nonetheless, in an abundance of caution, LGS has decided to field modify the 9 units it has sold since 2014 on which a snapped winch cable could cause the rear door to freefall and injure a bystander. These are units equipped with a winch cable as the sole means of securing the rear door.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Bystander injury from freefalling rear door.

Description of the Cause : NR

Identification of Any Warning that can Occur : Winch cable would show signs of wear or damage.

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

LGS heard about two incidents occurring on competitors' box trailers where the winch cable securing the rear door snapped, causing the rear door to freefall and strike bystanders. LGS learned of the latest occurrence in October, 2021. After learning of the second occurrence on competitors' trailers, in an abundance of caution, even though it has never received any reports of incidents involving winch cables on its trailers, LGS decided to field modify the 9 trailers it has made since 2014 on which a snapped winch cable could cause the rear door to freefall and injure a bystander. .

Description of Remedy :

Description of Remedy Program : LGS is adding a BLOCSTOP fall arrestor/speed brake. The BLOCSTOP operates at a certain "speed limit" which is directly related to the speed of the cable passing through the BLOCSTOP. In the event of overspeed the clamping mechanism, which had been previously set under tension, is released - the clamping jaws grip the cable and hold the rear door safely and instantly. LGS will add the BLOCSTOP to the 9 affected trailers at LGS's sole cost and expense.

How Remedy Component Differs from Recalled Component : It is a redundant device.

Identify How/When Recall Condition was Corrected in Production : LGS has not and will not sell trailers equipped with a winch cable as the sole support for the rear door.

Recall Schedule :

Description of Recall Schedule : Over the course of November and December 2021, LGS has contacted owners of 8 of the 9 affected vehicles to arrange for the free field modification. The ninth vehicle was sold by a dealership that dissolved, and LGS is continuing to work to try to identify and locate the owner of that trailer.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported