

# Part 573 Safety Recall Report

## 22V-004

**Manufacturer Name :** Forest River, Inc.

**Submission Date :** JAN 07, 2022

**NHTSA Recall No. :** 22V-004

**Manufacturer Recall No. :** 51-1449



### Manufacturer Information :

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

### Population :

Number of potentially involved : 1,164

Estimated percentage with defect : 100 %

### Vehicle Information :

Vehicle 1 : 2021-2022 Forest River Inc. Sanibel Fifth Wheel Recreational Vehicles

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Using the provided date range indicated by the supplier, Forest River was able to build the scope of vehicles

U.S. - See Spreadsheet for specific Model and Quantity

Production Dates : JUN 26, 2020 - DEC 22, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 2 : 2021-2022 Forest River Inc. Cardinal Fifth Wheel Recreational Vehicle

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Using the provided date range indicated by the supplier, Forest River was able to build the scope of vehicles

U.S. - See Spreadsheet for specific Model and Quantity

Production Dates : JUN 26, 2020 - DEC 22, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 3 : 2021-2022 Forest River Inc. Crusader Fifth Wheel Recreational Vehicle

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Using the provided date range indicated by the supplier, Forest River was able to build the scope of vehicles  
U.S. - See Spreadsheet for specific Model and Quantity

Production Dates : JUN 26, 2020 - DEC 22, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 4 : 2021-2022 Forest River Inc. Continental Cargo Trailers

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Using the provided date range indicated by the supplier, Forest River was able to build the scope of vehicles  
U.S. - See Spreadsheet for specific Model and Quantity

Production Dates : JUN 26, 2020 - DEC 22, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

## Description of Defect :

Description of the Defect : Per Sailun Tire Americas, Inc.: The defect is associated with a steel belt package design change, which could contribute to a tread belt separation or tread delamination. If any customer or user is in possession of the recalled tires, please DISCONTINUE USE IMMEDIATELY. If you have any recalled tires in your inventory, please segregate and do not sell or use.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The steel belt may separates or the tread delaminates, the risk of a crash increases.

Description of the Cause : NR

Identification of Any Warning that can Occur : None

## Involved Components :

Component Name 1 : Sailun tire ST235/80R16/G

Component Description : Sailun tire ST235/80R16/G with DOT factory code "DOT 1YJ" and date code 2020-4120

Component Part Number : Sailun tire ST235/80R16/G

### Supplier Identification :

#### Component Manufacturer

Name : Sailun Tire Americas, Inc

Address : 1 Kenview Boulevard

Brampton Foreign States 00 L6T 5E6

Country : Canada

### Chronology :

On January 3, 2022, the tire supplier of the recall issued by Sailun Tire Americas (21T018) notified Forest River's Office of Corporate Compliance "OCC". OCC began an investigation to identify which manufacturing plants were involved.

On January 7, 2022, Forest River's Corporate Recall Committee was notified of the pass through recall.

## Description of Remedy :

Description of Remedy Program : Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy. The tires will be inspected for specific information relating to the DOT code. All listed brands and sizes within the identified DOT date and factory code range will be replaced.

Dealers/Service Centers: DOT date range identified by factory code 1YJ and the last four digits of the DOT code 2020 – 4120 are in the affected range. If the factory code is MW, the tire(s) are not affected. The date of manufacture (last four characters in the DOT Code) can be found molded onto the tire near the bead. For the affected lot(s) the plant code (first three characters in the DOT Code) will be 1YJ and the last four characters will be the date code range (2020 - 4120).

If the tires are affected, please submit a claim on Dealer Connect, and Call the Forest River Brand Contact listed below to order the replacement tire (s).

What is the Forest River Customer Service Phone Numbers?

Crusader & Sanibel (574) 862-1025

Cardinal (574) 296-7700

Continental Cargo (503) 874-1102

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

Prime Time Service Facility Forest River, Inc.

Attn: WARRANTY MANAGER

200 SR 19 North

Wakarusa, IN 46573

Cardinal

Forest River, Inc.

Attn: WARRANTY MANAGER

3603 South Nappanee St.

Elkhart, IN 46517

Cargo Oregon

Forest River, Inc.

Attn: WARRANTY MANAGER

1204 Mill St

Silverton, OR 97381

**How Remedy Component Differs from Recalled Component :**

Only those tires within the listed DOT date range and factory code are affected. DOT date range identified by factory code 1YJ and the last four digits of the DOT code 2020 – 4120 are in the affected range. If the factory code is MW, the tire(s) are not affected.

Manufacturer Name : Sailun Tire Americas, Inc.

Address : 1 Kenview Boulevard

Brampton ON Canada 00 L6T 5E6

Company phone : 905-595-3593

Involved Component – Sailun tire ST235/80R16/G with DOT factory code "DOT 1YJ" and date code 2020-4120

Replacement Component - A Sailun tire(s) ST235/80R16/G or a ST235/80R16/G of another brand at no cost.

**Identify How/When Recall Condition was Corrected in Production :**

Per Sailun Tire Americas, Inc.: The modification to the steel belt package design was applied October 11, 2020 - DOT week 4220.

**Recall Schedule :****Description of Recall Schedule :**

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : FEB 16, 2022 - FEB 16, 2022

Planned Owner Notification Date : FEB 16, 2022 - FEB 16, 2022

\* NR - Not Reported