The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Manufacturer Recall No.: NR

Manufacturer Information :

Manufacturer Name : Lakota Corporation Address: PO Box 219 4 Stoutco Drive Bristol IN 46507 Company phone : 574-848-1636

Vehicle Information :

Vehicle 1:	2021-2022 Lakota Bighorn & Charger & Livestock
Vehicle Type :	TRAILERS
Body Style :	
Power Train :	NR
Descriptive Information :	still determining what trailers contain the recalled tires. removing trailers from the list that were a different plant number, total number of trailers 70. 68 US trailers and 2 in Canada.
Production Dates :	JUN 01, 2020 - DEC 31, 2020
VIN Range 1:	Begin : NR End : NR Not sequential

Description of Defect :

Description of the Defect : Sailun tires, tread belt separation or tread delamination FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk : risk of crash Description of the Cause : defect with a steel belt package design

Identification of Any Warning NR that can Occur:

Involved Components :

云 🔨 🕰


NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Number of potentially involved :

Estimated percentage with defect : 100 %

68





Population:

Manufacturer Name : Lakota Corporation Submission Date : JAN 31, 2022 NHTSA Recall No.: 22V-005

Part 573 Safety Recall Report

Component Name 1: Sailun Tire

Component Description : 16" tire DOT code 2020-4120

Component Part Number : 235/85R16 G

Supplier Identification :

Component Manufacturer

Name : Sailun Tire Americas Address : NR NR Country : United States

Chronology :

Tredit Tire and Wheel sent Lakota trailers a letter indicating Sailun Tire Americas has issued a recall, 21T-018

Description of Remedy :

Description of Remedy Program :	The defect is associated with a steel belt package design change that could contribute to a tread belt separation or tread delamination
How Remedy Component Differs from Recalled Component :	the new ties will not have the steel belt package defect
dentify How/When Recall Condition was Corrected in Production :	I will have to reach out to Sailun to find out.

Recall Schedule :

I

Description of Recall Schedule :letters will be issues to dealers and retail owners.Planned Dealer Notification Date :FEB 11, 2022 - FEB 11, 2022Planned Owner Notification Date :FEB 18, 2022 - FEB 18, 2022

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573