

Part 573 Safety Recall Report

22V-005

Manufacturer Name : Lakota Corporation**Submission Date :** JAN 07, 2022**NHTSA Recall No. :** 22V-005**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Lakota Corporation

Number of potentially involved : 100

Address : PO Box 219

Estimated percentage with defect : 100 %

4 Stoutco Drive Bristol IN 46507

Company phone : 574-848-1636

Vehicle Information :

Vehicle 1 : 2021-2022 Lakota Bighorn & Charger

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : still determining what trailers contain the recalled tires.

Production Dates : JUN 01, 2020 - DEC 31, 2020

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : Sailun tires, tread belt separation or tread delamination

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : risk of crash

Description of the Cause : defect with a steel belt package design

Identification of Any Warning : NR
that can Occur :**Involved Components :**

Component Name 1 : Sailun Tire

Component Description : 16" tire DOT code 2020-4120

Component Part Number : NR

Supplier Identification :**Component Manufacturer**

Name : Sailun Tire Americas

Address : NR

NR

Country : United States

Chronology :

Tredit Tire and Wheel sent Lakota trailers a letter indicating Sailun Tire Americas has issued a recall, 21T-018

Description of Remedy :

Description of Remedy Program : The defect is associated with a steel belt package design change that could contribute to a tread belt separation or tread delamination

How Remedy Component Differs from Recalled Component : the new ties will not have the steel belt package defect

Identify How/When Recall Condition was Corrected in Production : I will have to reach out to Sailun to find out.

Recall Schedule :

Description of Recall Schedule : letters will be issues to dealers and retail owners.

Planned Dealer Notification Date : FEB 11, 2022 - FEB 11, 2022

Planned Owner Notification Date : FEB 18, 2022 - FEB 18, 2022

* NR - Not Reported