



**S-Series™**  
BACKED BY McNEILUS

February 2022

## IMPORTANT SAFETY RECALL 22V-009

Dear Oshkosh Vehicle Owner:

Ref: NHTSA U-Bolts Securing Front Axle May Fail 22V-009

VIN: <<NOTE: Either insert VIN or reference attached VIN list>>

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Oshkosh has decided that a defect which relates to motor vehicle safety exists in your Oshkosh S-Series Front Discharge Mixer. These vehicles were built between 2018-2021.

### **! I M P O R T A N T !**

- Your Oshkosh vehicle is being recalled.
- Contact Oshkosh at 1-888-686-7278 for any questions.
- This recall repair will result in **no cost** to you.

#### **Why is a recall being conducted?**

A concern affecting safety exists in some Oshkosh S-Series Front Discharge Mixers. Trucks have been identified that are equipped with front axle U-bolts that were manufactured incorrectly and do not meet the required material specifications. The defect may cause the front axle U-bolts to loosen or fall off, resulting in the front axle shifting or the axle becoming dislocated from the vehicle. This bulletin provides instruction on replacing the front axle U-bolts.

#### **What are we doing about the problem?**

Oshkosh will provide customers with Instructions on how to install a new front axle U-Bolts. Customers would purchase the parts, perform the repairs, and then file parts/labor reimbursement through normal warranty process. Customers can also choose to have an Oshkosh service center perform the inspection and repair work free of charge.



**S-Series™**  
BACKED BY McNEILUS

**What should you do?**

- Repairs should take less than 1.5 hours.
- Customers can also choose to have an Oshkosh service center perform the inspection and repair work free of charge.

**What if you no longer own this vehicle?**

If you no longer own this vehicle, please contact Oshkosh at 1-888-686-7278 to assist us in updating our records.

**Who should you contact if you have further questions or concerns?**

If you have further questions, please contact Oshkosh at 1-888-686-7278 to allow us to assist you.

**If you have leased this vehicle to another person, federal regulations require you to send a copy of this notice to your lessee by first-class mail within ten days of your receipt of this notice.**

If Oshkosh fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to:

The Administrator, National Highway Traffic Safety Administration  
1200 New Jersey Avenue, SE.,  
Washington, DC 20590;  
or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153);  
or go to <http://www.safercar.gov>.

We apologize for any inconvenience this safety recall may cause, but your safety is our first concern.

Sincerely,

OSHKOSH CORPORATION