



PETERBILT MOTORS COMPANY
A **PRIMOR** COMPANY
1700 WOODBROOK STREET
DENTON, TEXAS 76205-7864
940-591-4000



IMPORTANT SAFETY RECALL INFORMATION

Issued in Accordance
With Federal Law



FIRST-CLASS MAIL
U.S. POSTAGE
PAID
CLEVELAND, OH
Permit No. 469



*****SGLP



22PBA



T1 P1
9001

RECALL NOTICE

Recall Notice: 22PBA

IMPORTANT SAFETY RECALL

April 8, 2022

Subject: Safety Recall: 22PBA - Unintended Chassis Fairing Step Movement

NHTSA: 22V016

EXPIRATION DATE: NONE

This notice applies to your vehicle. Your VIN(s) can be found on the bottom or back of this page.

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt has decided that a defect which relates to motor vehicle safety exists in certain Model 579 vehicles equipped with a cab step integrated into the chassis fairing. Chassis fairings may become loose at one attachment point, allowing minor unintended movement and risk of injury while entering and exiting the cab.

What is the problem?	Chassis fairings with integrated cab step may become loose, allowing minor unintended movement.
What will your dealer do?	Your dealer will add a support bracket to reinforce the chassis fairing(s) and replace the hardware.
What should you do?	Contact your dealer to schedule the repair.

Peterbilt Motors Company has initiated this recall to remedy the issue with no charge to you. Please contact your Peterbilt dealer to schedule an appointment for these services. To find your Peterbilt dealer, please visit the Dealer Locator at www.Peterbilt.com or scan the QR code. When contacting your Peterbilt dealer, reference the Safety Recall number and the NHTSA number. This repair may take up to 1 hour of labor depending on dealer scheduling.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall, or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St, Denton, TX 76205, Attn: Customer Service Department.

If you conclude that Peterbilt has not enabled you to remedy this defect in a reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner. Please send all known ownership and address changes to PBDiv.Warranty.Docs@paccar.com.

We apologize for any inconvenience this preventive procedure may cause and thank you for your participation in helping Peterbilt provide the highest levels of customer satisfaction and service expertise. We value your business and appreciate your ongoing loyalty to Peterbilt and its dealer network. Industry-leading quality, performance and reliability are hallmarks of Peterbilt products, and we thank you for making Peterbilt your truck of choice.

Sincerely,



Michelle Ponsonby
Director of Customer Service
Peterbilt Motors Company

Scan this QR code to open the
Peterbilt Dealer Locator.



Our records indicate that these vehicles are affected by 22PBA and are owned by [REDACTED]

