

Part 573 Safety Recall Report

22V-021

Manufacturer Name : Hino Motors Sales U.S.A., Inc.

Submission Date : JAN 21, 2022

NHTSA Recall No. : 22V-021

Manufacturer Recall No. : AANTO



Manufacturer Information :

Manufacturer Name : Hino Motors Sales U.S.A., Inc.

Address : 45501 Twelve Mile Road

Novi MI 48377

Company phone : 248-699-9300

Population :

Number of potentially involved : 1

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2021-2021 HINO NJ8A

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : ALL

Power Train : DIESEL

Descriptive Information : Hino identified a single subject vehicle with a replacement air brake hose assembly in which the end fittings of that air brake hose lacked a manufacturer designation. The parts that are subject to the recall, which were distributed through the Service Parts Network, may not contain a manufacturer designation pursuant to 49 C.F.R. 571.106 S7.2.2(b) and 49 C.F.R. 571.106 S7.2.3.1.

Production Dates : JAN 31, 2020 - JAN 31, 2020

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Noncompliance :

Description of the Noncompliance : On certain replacement part air brake hose assemblies, air brake hose end fittings may not have a designation for identifying the manufacturer. Therefore, the air brake hose end fittings may not contain the designation requirement of FMVSS No.106 S7.2.2 (b) and FMVSS No.106 S7.2.3.1.

FMVSS 1 : 106 - Brake hoses

FMVSS 2 : NR

Description of the Safety Risk : An air brake hose end fitting without the manufacturer designation may not be traceable should there be a concern with performance. Hino has determined the brake hose assembly, although missing the manufacturer's designation, meets all of the performance requirements of FMVSS 106.

Description of the Cause : A change in replacement part air brake hose assembly supplier resulted in the missing manufacturer designation.

Identification of Any Warning that can Occur : N/A

Involved Components :

Component Name 1 : HOSE SUB-ASSY, AIR

Component Description : AIR BRAKE HOSE

Component Part Number : S4703-E0W40

Supplier Identification :**Component Manufacturer**

Name : MEIJI FLOW SYSTEMS CO., LTD.

Address : Kasei-Machi 31-7, Nobusawa

Kanagawa Prefecture Ashigarakami-Gun Foreign States 256-0026

Country : Japan

Chronology :

September 2021 ~ December 2021

During the development of the new model vehicle, it was discovered that a particular replacement air brake hose assembly did not have the manufacturer designation on the air brake hose end fittings. Investigation revealed that a replacement air brake hose assembly was sold via a Hino dealer and installed in a single vehicle. No other affected vehicles were identified.

January 17, 2022

Based on the investigation above, Hino confirmed that the subject air brake hose assembly meets all requirements of FMVSS 106 with the exception of the manufacturer's designation specifically required for assemblies under FMVSS 106 S7.2.3. Therefore, Hino has determined to perform a recall on the air brake hose assemblies which were distributed through the service parts network.

Description of Remedy :

Description of Remedy Program : For the subject affected vehicle, the dealer will directly contact the owner and replace the subject hose free of charge.

How Remedy Component Differs from Recalled Component : The remedy air brake hose assembly has the manufacturer designation on the end fittings.

Identify How/When Recall Condition was Corrected in Production : N/A

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported