

UPDATE: Recall 22V-023 Rear Strut Link K1600 GT, K1600 GTL and K 1600 B
MY 2017-2020

BMW Motorrad is announcing an update regarding Safety Recall 22V-023.

The range of affected units has been expanded to Model Year 2017-2020 K1600 GT, K 1600 GTL and K 1600 B produced inclusively between 10/11/2016 and 06/29/2020. Potentially affected motorcycles were equipped with a rear strut link which, over time, may become damaged. This could affect rider handling and control and increase the risk of a crash.

The additional affected vehicles will be flagged with campaign code 0000334600 shortly. If you have a vehicle in your new/used inventory matching the above description it cannot be retailed until repaired. Due to the older production range, only a handful of vehicles in dealer inventory may be affected.

The fix will be to replace the rear strut link. Customers will be receiving a letter informing them of the recall in the next 60 days.

Service bulletin [SIB 33 01 22 has been published in TIS](#) and linked to the campaign code. Part ordering for the suspension link will be done using the special campaign ordering process outlined in this Service Bulletin.

Aug 18, 2022