

Lisa Sampson

From: Lisa Sampson
Sent: Thursday, April 14, 2022 6:40 PM
To: [REDACTED]
Cc: Dave Reichman
Subject: Truck at PDI - Impacted by 22V-025 Recall - [REDACTED]
Attachments: RCLRPT-22V025-8325_Rosenbauer's 573 A1.PDF; 22V-025 Meritor Recall - Steps for PDI Trucks.pdf

Hello – as you know, we have been working with Meritor regarding their rear axle recall. Unfortunately, we had to add again to our population based on their recommendation of impacted serial numbers. This means that we weren't able to have Meritor inspect these two trucks while it was in Production prior to shipment to you for PDI. Please see the attached document which will outline the steps you need to take to resolve the recall prior to customer delivery.

We realize that this isn't an ideal situation but we truly appreciate you and your team helping us to ensure we have safe vehicles on the road. I have also attached more information regarding the recall that Rosenbauer has filed which we will be updating soon. We will send official notifications to customers in the next 7 days as well as provide you with a complete list of impacted trucks in your network.

Please reach out if you have any problems with this procedure.
Thank you for your help.

Drive AXLE SN	Drive Axle Model #	VIN	Chassis WO	Job	Dealer
LRS01652801	Meritor 180 Series	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
LRS01568900	Meritor 180 Series	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]



Lisa Sampson

Rosenbauer America, LLC
Compliance Manager



www.RosenbauerAmerica.com