




***** IMPORTANT SAFETY RECALL *****
NHTSA Recall No. 21E-099
Cummins Campaign #C2532

March 11, 2022



****AUTO**ALL FOR AADC 400



X12 Engines for NHTSA Recall 21E-099:

Engine Serial Number	Vehicle Model	Vehicle Identification Number (VIN)
7508		

Cummins Inc.
 Box 3005
 Columbus, IN 47202-3005 USA
 Mail Code: 40911
 Phone: 1 800 CUMMINS
 care.cummins.com



***** IMPORTANT SAFETY RECALL *****
NHTSA Recall No. 21E-099
Cummins Campaign #C2532

March 11, 2022

Dear Cummins Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Cummins Inc. has decided that a defect which relates to motor vehicle safety exists in certain Cummins X12 Engines that were manufactured between April 26, 2016 and November 1, 2021 and for installation in mixer, truck, coach, emergency vehicle, refuse truck, recreational vehicle and crane applications.

This notice applies to the engines(s)/vehicles(s) listed on the enclosed table.

You previously received a letter informing you of this recall and advising you that Cummins was developing a remedy. A remedy is now available for your engine/vehicle.

WHAT IS THE PROBLEM?

The fuel tubes between the fuel rail and the injectors for cylinders 4, 5 and 6 may be susceptible to cracking, resulting in a high pressure fuel leak. A high pressure fuel leak in the presence of an ignition source may increase the risk of a fire.

WHAT ARE WE DOING ABOUT THE PROBLEM?

Cummins has released field Safety Campaign #C2532, X12 CM2350 X119B and X12 CM2450 X137B Fuel Injector Supply Line Safety Campaign to correct this condition by replacing the fuel tubes with new fuel tubes and installing vibration isolators for cylinders 4,5 and 6. This campaign is currently available at Cummins Distributors and authorized Warranty dealers. The repair will be completed free of charge and most applications will require approximately 2 hours to complete.

WHAT SHOULD YOU DO?

Contact the nearest Cummins Distributor or authorized Warranty Dealer to arrange to have this campaign performed on your engine. The distributor or dealer will work with you to schedule the best date to complete the repair.

In the meantime, Cummins advises you to periodically check the injector fuel tubes for signs of leaking and to seek repairs if leaks are identified. If a leak occurs, the operator may smell diesel fuel or observe a mist.



WHO SHOULD YOU CONTACT IF YOU HAVE FURTHER QUESTIONS OR CONCERNS?

If you have questions or concerns about this recall, please contact your local Cummins Distributor or authorized warranty dealer. You may also contact Cummins Care at 1-800-CUMMINS (1-800-286-6467), or visit our website at care.cummins.com.

If you have a complaint relative to this recall, you may report it to the following:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, DC 20590

You may also call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you have not registered your Cummins product, please complete the enclosed registration card or register your product at <https://prodreg.cummins.com/prodreg/#/webform/contactInfo>.

If you are no longer the owner of the generators(s) listed on the enclosed table, please forward this notice to the new owner or provide the new owner's contact information to Cummins so that we can notify them of this recall.

Federal law requires vehicle lessors receiving this recall notice to forward a copy of this notice to the lessee within ten (10) days. Also, it is a violation of Federal law for a dealer to deliver a new vehicle or equipment covered by this recall notice under a sale or lease until the defect has been remedied.

Cummins is taking this action in the interest of your safety and satisfaction with our products. We apologize for any inconvenience and thank you for your attention to this matter.

Sincerely,

Campaign Administrator
Cummins Inc.