

# Part 573 Safety Recall Report

# 22V-041

**Manufacturer Name :** Forest River, Inc.**Submission Date :** JAN 28, 2022**NHTSA Recall No. :** 22V-041**Manufacturer Recall No. :** 81-1462**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

**Population :**

Number of potentially involved : 21

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2022-2022 Forest River Inc. Vengeance Fifth Wheels

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Forest River changed the tire size used on this model. Units in this campaign include all units from the time the change, on line date of 12/1/2021 or later was made ending when the error was found and corrected in our system.

2022 VENGEANCE VGF383G2-81 21

Grand Total 21

Production Dates : DEC 10, 2021 - JAN 13, 2022

VIN Range 1 : Begin : NR

End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : When the data was entered into the system for this model the front axle tire pressure was entered at 50psi and should have been 80. The rear axle was entered with the correct pressure of 80psi. Therefore the Federal Placard indicates the incorrect tire air pressure.

FMVSS 1 : 120 - Wheels and rims- other than passenger cars

FMVSS 2 : 567 - Certification

Description of the Safety Risk : If the tire is not inflated to 80psi it may cause the tire to fail, increasing the risk of a crash.

Description of the Cause : Clerical Error

Identification of Any Warning that can Occur : Tire would have a belly at the bottom and visually appear under inflated.

**Involved Components :**

Component Name 1 : Federal Placard

Component Description : Federal Placard

Component Part Number : N/A

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

On 1/17/2022, Forest River corrected the tire pressure information entered for this model and began its review of all other model ran in the plant since 12/1/2021.

After an extensive review it was determined that the VGF383G2-81 was the only model affected.

On 1/25/2022 Forest River was able to determine the scope of vehicles.

On 1/28/2022 Forest Rivers Corporate Recall Committee voted to recall

## Description of Remedy :

Description of Remedy Program : Forest River has notified dealerships of this recall and have provided them with remedy instructions to install these Federal Placards if you are uncomfortable installing them yourself. You may have the recall corrected at any Forest River dealership. However, it is preferable if you have your selling dealership perform the remedy. Forest River completely covers your cost for the remedy; you will not receive any bill of sale for anything covered under the above recall number.

If you are not comfortable with installing these labels:

Please contact your dealer immediately and request a service appointment to schedule the free remedy. The vehicle Owner is responsible for arranging to have the work completed. Please state you have been notified by Forest River of having a recall in process for your vehicle and provide the recall number for the dealership. It is also helpful to the dealership to have a copy of this letter when you take your vehicle in for the recall remedy.

You may also visit [www.forestriverinc.com](http://www.forestriverinc.com) for dealer locations.

What is the Forest River Customer Service Phone Number? 260-499-2100

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

Cherokee  
Forest River, Inc.  
Attn: WARRANTY MANAGER  
1500 N Detroit St.  
Lagrange, IN 46761

How Remedy Component Differs from Recalled Component : The new federal placard will have the correct tire pressure listed at 80 opposed to 50

Identify How/When Recall Condition was Corrected in Production : On 1/17/2022 the data was corrected in our system to reflect 80psi inflation for the tires installed on the front axle.

## Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out

as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : MAR 09, 2022 - MAR 09, 2022

Planned Owner Notification Date : MAR 09, 2022 - MAR 09, 2022

\* NR - Not Reported