

# Part 573 Safety Recall Report

## 22V-046

**Manufacturer Name :** Jayco, Inc.**Submission Date :** FEB 01, 2022**NHTSA Recall No. :** 22V-046**Manufacturer Recall No. :** 21T-018**Manufacturer Information :****Manufacturer Name :** Jayco, Inc.**Address :** 903 South Main Street

PO Box 460 Middlebury IN 46540

**Company phone :** 800-283-8267**Population :****Number of potentially involved :** 56**Estimated percentage with defect :** 100 %**Vehicle Information :****Vehicle 1 :** 2021-2022 Jayco Towable North Point, Pinnacle**Vehicle Type :** TRAILERS**Body Style :** OTHER**Power Train :** NR**Descriptive Information :** Jayco determined the scope from its production records.**Production Dates :** FEB 26, 2021 - JAN 14, 2022**VIN Range 1 : Begin :** 1UJCJ0BS1N1LB0308 **End :** 1UJCJ0BVXN1LF0123☒ Not sequential**Description of Defect :**

**Description of the Defect :** Sailun Tire Americas, Inc. (Sailun) reported that due to a steel belt package design change the affected tires may experience a tread belt separation or tread delamination. If any customer is in possession of the recalled tires, they are advised to discontinue use immediately.

**FMVSS 1 :** NR**FMVSS 2 :** NR

**Description of the Safety Risk :** Belt separation and tread delamination could lead to loss of vehicle control, increasing the risk of a crash.

**Description of the Cause :** Certain Sailun tires may contain a manufacturing defect.

**Identification of Any Warning** None  
**that can Occur :**

**Involved Components :**

Component Name 1 : Sailun tire ST235/80R16/G

Component Description : Sailun tire ST235/80R16/G with DOT factory code "DOT 1YJ" and date code 2020-4120

Component Part Number : 2024517, 2024518, 2026415, 2030046

### Supplier Identification :

#### Component Manufacturer

Name : Sailun Tire Americas, Inc.

Address : 1 Kenview Boulevard  
Brampton Foreign States L6T 5E6

Country : Canada

### Chronology :

1/17/2022 Jayco Compliance received a letter from our supplier Tredit Tire & Wheel Company, Inc. stating that a defect which relates to motor vehicle safety exists in certain Sailun Speciality Trailer (ST) branded tires. Sailun Tire Americas has not provided a chronology of events that were the basis for their determination that the defect related to motor vehicle safety, warranty claims, field or service reports or other information.

1/27/2022 Warranty Incident Review Committee (WIRC) discussed this incident and elevated to the Corrective and Preventive Action Committee (CPAC). 1/19/2022 CPAC met to discuss this incident and elevated this incident to the Safety Steering Committee (SSC). On 1/27/2022 SSC met and voted that a safety recall was appropriate for this incident.

### Description of Remedy :

Description of Remedy Program : Sailun will replace the tires free of charge.  
Repairs made prior to the recall will be reimbursed in accordance with our Recall Reimbursement Plan on file with NHTSA.

How Remedy Component Differs from Recalled Component : Remedied units will have tires that were not manufactured during the time period that defective tires were produced.

Identify How/When Recall Condition was Corrected in Production : Sailun reported that the modification to the steel belt package design was applied October 11, 2020 – DOT week 4220.

### Recall Schedule :

Description of Recall Schedule : Jayco will notify its dealers and affected retail owners.

Planned Dealer Notification Date : MAR 28, 2022 - MAR 28, 2022

Planned Owner Notification Date : MAR 28, 2022 - MAR 28, 2022

\* NR - Not Reported