

[Next Unread Message](#)[View Message](#)

<b>Sent on</b>	02	02	2022	<b>Expires on</b>	04	21	2022
<b>From</b>	Powersports Quality Center						
<b>Subject</b>	STOP SALE NOTICE: 2021 CBR1000RR-R (SP) Oil Cooler Pipe						

February 2, 2022

Re: STOP SALE NOTICE: 2021 CBR1000RR-R (SP) Oil Cooler Pipe

Dear Honda Dealer:

Honda is launching a SAFETY RECALL on CERTAIN 2021 CBR1000RR-R (SP) motorcycles to install a heat guard and possibly replace the oil cooler outlet pipe. Under certain conditions, if the motorcycle is ridden in 1st gear above 5,000 rpm for an extended period, the oil cooler pipe may melt due to radiant heat from the exhaust pipe. A melted oil cooler pipe may leak oil, increasing the risk of a crash, injury, or fire. Effective immediately, you MUST NOT SELL any affected NEW or USED 2021 CBR1000RR-R (SP) motorcycle until it is repaired according to the associated Service Bulletin.

**AFFECTED UNITS**

CERTAIN NEW or USED 2021 CBR1000RR-R (SP).

- To search for applicable recalls on a specific unit, you MUST use *Unit Information* on *iN*, available February 2, 2022.
- To manage your affected inventory, use your dealer *eResponsibility Report* on *iN*, available February 3, 2022.

**SERVICE BULLETIN**

*Service Bulletin: CBR1000RR-R #2*, which includes all the information relating to this Safety Recall, is expected to be issued by the end of business Thursday, February 10, 2022.

**PARTS INFORMATION**

Parts will be available in late February 2022. All parts needed for this repair will be under *TechLine* control. When available, you MUST contact *TechLine* to have these parts released.

**CUSTOMER NOTIFICATION**

American Honda intends to mail customer letters to all owners of affected 2021 CBR1000RR-R (SP) motorcycles in March 2022. Customers will be informed that their vehicle may be affected by a safety related defect and to avoid extended 1st gear usage over 5,000 rpm. When parts are available in April 2022, a second mailing will advise customers of affected units to make an appointment with an authorized Honda dealer for repair.

Make sure all departments in your dealership are aware of this Safety Recall.

If you have any questions, please contact AHM TechLine through TechLine Connect on *iN*.

Sincerely,  
American Honda Motor Co., Inc.  
Powersports Division

MTB 17819 (2202)