



# Thor Motor Coach Recall Repair Instructions

Recall #	<b>22V-076 2022-062</b>		
Description/Title:	<b>Incorrect Ladder Placement</b>		
Affected Product Line(s):	<b>Certain model year 2022 Ace, Freedom Traveler, Hurricane, &amp; Windsport</b>		
Service Campaign # :	<b>RC000255</b>	Released Date:	<b>3/24/2022</b>
Repair Code:	<b>Inspect Only: TMCRC10108Y</b>  <b>Repair: TMCRC10108V</b>	Document Date:	<b>3/24/2022</b>
Time Allowed:	<b>Inspect Only: 0.1</b>  <b>Repair: 0.5</b>	Document Revision:	<b>A</b>

**Issue:**

It has been discovered that on certain model year 2022 Ace, Freedom Traveler, Hurricane, and Windsport units, the ladder may have been installed on the incorrect side of the motorhome. The ladder should be installed on the right (passenger) side except the 35M Hurricane/Windsport

**Tools:**

- Drill
- #17 Drill Bit
- Rivet Gun
- Caulk Gun
- Roof Sealant
- Ladder

**Parts:**

- Hurricane/Windsport Units
  - Order TMC Part Kit #**0517564**
    - Includes 16 rivets



## Thor Motor Coach Recall Repair Instructions

- Ace/Freedom Traveler Units
  - Order TMC Part Kit #**0517565**
    - Includes 32 rivets

### **Instructions:**

Please see instructions below pertaining to the type of unit you are repairing.

- *31C Hurricane/Windsport units*
  - Has rear egress window next to ladder. When inspecting this unit make sure the rear egress window opens correctly and does not hit the ladder. If the ladder does not allow the window to open correctly, the ladder will need to be moved and bodywork performed to repair the holes in the rear cap. If the window opens correctly you can proceed with installing the rivets to secure the rear ladder. Replace the screws at the roof mounting points and the two recessed mounting points at the bottom of the ladder.
  
- *Ace/Freedom Traveler units*
  - Will need to have all the screws in the ladder replaced with rivets.



1. Use a # 17 drill bit to pre-drill the holes for the rivets.
2. Install rivets in ladder and make sure the ladder is secured.



## Thor Motor Coach Recall Repair Instructions

3. Use shop supplies to reseal roof after rivet installation.