## **Recall Quarterly Report**

22V-098

Manufacturer Name : Mercedes-Benz USA, LLC NHTSA Recall No. / MFR Recall No. : 22V-098 /2022030015 Recall Subject : Unsecured Wiring May Deactivate Fused Components Owner Notification Beginning Date : APR 08, 2022 Owner Notification End Date: APR 08, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JAN 11, 2023	2022-4	6	3	0	0
2	OCT 13, 2022	2022-3	6	1	0	0
1	JUL 10, 2022	2022-2	6	1	0	0

This Document Last Updated : JAN 12, 2023

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.