



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

March 7, 2022

Mr. Scott Goeb  
Product Safety Manager  
Pierce Manufacturing  
2600 American Dr  
Appleton, WI 54912

NEF-107MR  
22V-116

**Subject:** Improperly Crimped Lifting Cable

Dear Mr. Goeb:

This letter serves to acknowledge Pierce Manufacturing's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

PIERCE/ARROW XT/2021

**Mfr's Report Date:** March 1, 2022

**NHTSA Campaign Number:** 22V-116

**Components:**

EQUIPMENT

**Potential Number of Units Affected:** 1

**Problem Description:**

Pierce Manufacturing (Pierce) is recalling one 2021 Arrow XT firetruck equipped with a Cummins generator set. The lifting cables may be improperly crimped.

**Consequence:**

An improperly crimped cable may come out of place during a lifting operation, possibly causing the generator set to fall, increasing the risk of injury.

**Remedy:**

Cummins will inspect the lifting cable, and either replace the cable or install a warning label, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Pierce's customer service at 1-888-974-3723.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).

**Please ensure the following requirements are met:**

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

**AMENDED 573 REQUIRED.**

Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. Please be reminded that all owners must be notified of the safety risk associated with this filing within 60 days of the 573 being submitted. If the remedy is not available at that time, mail the interim notice, following it with a second notice once the remedy becomes available. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If there are no owners involved in this recall, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

**AMENDED 573 REQUIRED.**

Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If your company does not have dealers or distributors, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

**AMENDED 573 REQUIRED.**

Based on the provided remedy plan, it appears that your company may not be able to provide the required recall completion rate quarterly reports. If another company intends to file the report with detailed information about your company's remedy counts, please state so in the remedy section of the 573.

**AMENDED 573 REQUIRED.**

**Please be reminded of the following requirements:**

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Pierce Manufacturing's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink that reads "Alex Ansley". The signature is fluid and cursive, with a checkmark-like flourish at the end.

Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement