




***** IMPORTANT SAFETY RECALL *****
NHTSA Recall No. 21E-075
Cummins Campaign #4495

October 8, 2021



Generator set(s) eligible for Cummins Campaign #4495

Generator Serial Number	Vehicle Model	Vehicle Identification Number (VIN)
A210867286		1F9 [REDACTED]



***** IMPORTANT SAFETY RECALL *****
NHTSA Recall No. 21E-075
Cummins Campaign #4495

October 8, 2021

Dear Cummins Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Cummins Inc. has decided that a defect which relates to motor vehicle safety exists in certain 6RBAB, 8RBAB, 10RBAB, 15RBAB generator sets that were manufactured between January 29, 2021 and May 13, 2021.

This notice applies to your 6RBAB, 8RBAB, 10RBAB, or 15RBAB generator set(s) listed in the table on the enclosed Generator Set serial number list.

WHY IS A RECALL BEING CONDUCTED?

The generator sets are equipped with lifting cables to be used during product assembly, installation, service or removal. The ferrule on the genset lifting cable may have been improperly crimped by the supplier. If this condition exists, the lifting cable may pull out of the ferrule during lifting operation, which may cause the genset to fall during assembly, installation, service or removal, possibly resulting in personal injury.

WHAT ARE WE DOING ABOUT THE PROBLEM?

Cummins has released field Safety Campaign #4495 RBAB Lift Cable Crimp Issue to correct this condition by inspecting the lifting cable and, if defective, replacing it with a properly crimped lifting cable. Repair parts are currently available at Cummins Distributors and authorized Warranty Dealers. The repair will be completed free of charge and most applications will require approximately 7 hours to complete.

WHAT SHOULD YOU DO?

If the generator set must be lifted or moved, DO NOT use the lifting cable until it has been inspected as part of this campaign. Instead, use an alternative method for lifting until the lifting cable can be inspected and, if necessary, replaced with a properly crimped lifting cable.



Contact the nearest Cummins Distributor or authorized Warranty Dealer to arrange to have this campaign performed on your generator set. The distributor or dealer will work with you to schedule the best date to complete this repair.

Federal law requires vehicle lessors receiving this recall notice to forward a copy of this notice to the lessee within ten (10) days. Also, it is a violation of Federal law for a dealer to deliver a new vehicle or equipment covered by this recall notice under a sale or lease until the defect has been remedied.

WHO SHOULD YOU CONTACT IF YOU HAVE FURTHER QUESTIONS OR CONCERNS?

If you have questions or concerns about this recall, please contact your local Cummins Distributor or authorized warranty dealer. You may also contact Cummins Care at 1-800-CUMMINS (1-800-286-6467) or visit our website at care.cummins.com.

If you have a complaint relative to this recall, you may report it to the following:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, DC 20590

You may also call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you are no longer the owner of the generator set(s) listed in the table below, please forward this notice to the new owner or provide the new owner's contact information to Cummins so that we can notify them of this recall.

Cummins is taking this action in the interest of safety and satisfaction with our products. We apologize for any inconvenience and thank you for your attention to this matter.

Sincerely,

Campaign Administrator
Cummins Inc.