

Part 573 Safety Recall Report

22V-117

Manufacturer Name : Keystone RV Company

Submission Date : MAR 02, 2022

NHTSA Recall No. : 22V-117

Manufacturer Recall No. : 22-424



Manufacturer Information :

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 95

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2022-2022 Crossroads Sunset 330SI

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : 330SI floor plans

Production Dates : NOV 30, 2021 - FEB 10, 2022

VIN Range 1 : Begin : 4YDTSSR2XN5351450 **End :** 4YDTSSR2XN5352159 Not sequential

Description of Defect :

Description of the Defect : It has been decided that the vehicles in the recall population have a circuit that is not properly protected by a ground-fault circuit interrupter (GFCI).

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The outside receptacle is not properly protected by a GFCI and is not installed according to code under NFPA 70, which could lead to an increased risk of personal injury.

Description of the Cause : The outside receptacle is not ground fault protected.

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : NA

Component Description : NA

Component Part Number : NA

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

2/16/2022 – Report was made during a routine audit that the outside receptacle was not GFCI protected.

2/17/2022 – Investigation opened. All affected Sunsets were put on hold and circuits were inspected. Range and scope to be determined.

2/25/2022 – Investigation concluded and scope completed.

Description of Remedy :

Description of Remedy Program : The remedy is to wire the circuit properly so that the outside receptacle is properly protected. Manufacturer Reimbursement Plan on file as of 10/07/2020. General reimbursement plan to be updated every two years. New vehicles are covered under warranty.

How Remedy Component Differs from Recalled Component : The outside receptacle will be properly protected once the circuit is wired properly.

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : APR 25, 2022 - APR 25, 2022

Planned Owner Notification Date : APR 25, 2022 - APR 25, 2022

* NR - Not Reported