

Safety Recall 22S13
Certain 2020-2022 Model Year F59 Commercial Stripped Chassis
Steering Column Intermediate Shaft to Steering Gear Box
Upper U-joint Bolt Inspection and Torque

AFFECTED VEHICLES

The following table contains a list of VINs for vehicles.

1F64F5KN1M0A20594
1F64F5KN1M0A20613
1F64F5KN3N0A01689
1F64F5KN4N0A01717
1F64F5KN5M0A20596
1F65F5KN0M0A17772
1F65F5KN0M0A17786
1F65F5KN0M0A19893
1F65F5KN0N0A01475
1F65F5KN0N0A01766
1F65F5KN1M0A14251
1F65F5KN1M0A14928
1F65F5KN1M0A17957
1F65F5KN2M0A17787
1F65F5KN2M0A17935
1F65F5KN3M0A14249
1F65F5KN3M0A14252
1F65F5KN3M0A17863
1F65F5KN4M0A18018
1F65F5KN4M0A19010
1F65F5KN5M0A14253
1F65F5KN5M0A14933
1F65F5KN5M0A14947
1F65F5KN5M0A17931
1F65F5KN5M0A19923
1F65F5KN6M0A17579
1F65F5KN6M0A18053
1F65F5KN7M0A14934
1F65F5KN7M0A19258
1F65F5KN8M0A12447
1F65F5KN8M0A14490

Safety Recall 22S13
Certain 2020-2022 Model Year F59 Commercial Stripped Chassis
Steering Column Intermediate Shaft to Steering Gear Box
Upper U-joint Bolt Inspection and Torque

1F65F5KN8M0A18913
1F65F5KN8M0A19138
1F65F5KN8M0A19205
1F65F5KN8N0A01451
1F65F5KN9M0A14482
1F65F5KNXM0A14488
1F65F5KNXM0A14491
1F65F5KNXM0A16791
1F65F5KNXM0A17942
1F65F5KNXM0A19352
1F66F5KN0M0A17596
1F66F5KN1M0A14156
1F66F5KN1M0A17364
1F66F5KN2N0A04866
1F66F5KN3M0A10349
1F66F5KN3M0A17365
1F66F5KN4M0A17472
1F66F5KN4M0A17519
1F66F5KN4M0A17598
1F66F5KN5N0A02982
1F66F5KN7M0A17403
1F66F5KN7M0A17420
1F66F5KN7M0A17983
1F66F5KN9M0A17533
1F66F5KN9M0A17595
1F66F5KNXN0A02847
1F64F5KN4M0A02526
1F65F5KN3M0A12453
1F65F5KN3M0A12677
1F65F5KN4M0A12090
1F65F5KN5L0A01419
1F65F5KN5M0A02605
1F65F5KN7L0A10462
1F65F5KN7M0A08020

Safety Recall 22S13
Certain 2020-2022 Model Year F59 Commercial Stripped Chassis
Steering Column Intermediate Shaft to Steering Gear Box
Upper U-joint Bolt Inspection and Torque

1F65F5KN7M0A12648
1F65F5KN9M0A12523
1F65F5KNXL0A16899
1F66F5KN7M0A05414
1F66F5KN8L0A15013
1F66F5KN8M0A10444
1F66F5KNXL0A10346