



# VOLKSWAGEN DEALER COMMUNICATION

## REVISION – Safety Recall 97GF / Front Door Wiring Harness

**This notice is for:**

- |                    |                      |                          |
|--------------------|----------------------|--------------------------|
| ✓ Dealer Principal | ✓ Service Manager    | ✓ Warranty Administrator |
| ✓ General Manager  | ✓ Parts Manager      | ✓ Technicians            |
| ✓ Sales Managers   | ✓ Service Consultant |                          |

**Date:** September 22, 2022

**Revision Summary:**

The 97GF Safety Recall circular has been revised to include an updated fault code table.

**IMPORTANT!** Please review any current parts orders to confirm they are still needed with the current published fault codes in the revised circular.

Please see the revised circular for Safety Recall 97GF located in ELSA and ServiceNet for additional information.

**IMPORTANT REMINDER: VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS**

**New Vehicles in Dealer Inventory:** It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

**Pre-Owned Vehicles in Dealer Inventory:** Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.

**-END OF MESSAGE-**

*Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Volkswagen Public Relations.*