

Part 573 Safety Recall Report

22V-156

Manufacturer Name : Roadtrek Inc.

Submission Date : JUN 14, 2022

NHTSA Recall No. : 22V-156

Manufacturer Recall No. : 2022-02



Manufacturer Information :

Manufacturer Name : Roadtrek Inc.

Address : 20 Tyler Street

Cambridge 00 N1T0E4

Company phone : 519-745-1160

Population :

Number of potentially involved : 10

Estimated percentage with defect : 100 %

Vehicle Alterer Information :

Vehicle 1 : 2020-2021 Roadtrek Inc SS Agile

Descriptive Information : On Mar 2, 2022 A customer contacted us concerned about tire wear on the front tires of his vehicle. The pursuant investigation discovered that the tire pressure label on the vehicle was in fact correct and there was no safety issue. But the pursuant investigation led to the realization that the 2020 MY chassis had been ordered with the A50 front suspension option which provided for an increased GVWR which required an increase in the front tire pressure from 46 psi to 52 psi. We did not realize this new option was ordered or that this required these changes. The investigation revealed that there were only 10 of the MY 2020 vehicles that labelled with the incorrect front tire pressure labels as well as understated GVWR and OCCC but was the correct limits for the 46 psi front tire pressure. This label information was corrected in production on Nov 18, 2021.

Production Dates : NOV 13, 2020 - NOV 18, 2021

Description of Defect :

Description of the Defect : Tire pressure label states incorrect front tire pressure of 46 psi rather than the correct 52 psi.

FMVSS 1 : 138 - Tire pressure monitoring systems

FMVSS 2 : NR

Description of the Safety Risk : The incorrect front tire pressure could cause the Tire Pressure Monitoring System to indicate a low tire pressure warning. Incorrect tire pressure could cause the vehicle stability control systems to malfunction resulting in possible loss of control of the vehicle and an increased risk of a crash.

Description of the Cause : tire pressure label incorrectly states the front tire pressure to 46 psi rather than the correct pressure of 52 psi

Identification of Any Warning that can Occur : TPMS might provide a low tire pressure warning and indicate that the correct front tire pressure is 52 psi.

Involved Components :

Component Name : tire pressure label

Component Description : label

Component Part Number : NR

Supplier Identification :**Component Manufacturer**

Name : Roadtrek Inc

Address : 20 Tyler St.

Cambridge, Ontario Canada Foreign States N1T 0E4

Country : Canada

Chronology :

On Mar 2, 2022 a customer contacted Roadtrek Customer Support asking about uneven tire wear on his front tires. The pursuant investigation led to the realization that the 2020 MY vehicles had been ordered with the A50 stronger front suspension option which increased the GVWR from 3878 kg to 4105 kg and accordingly required the front tire pressure to be increased from 46 psi to 52 psi. The customer that had originally complained actually did have the correct front tire pressure of 46 psi for his MY 2019 chassis that did not have the A50 option.

Description of Remedy :

Description of Remedy Program : a new tire pressure label will be sent out to the owners of all of the effected vehicles for them to install on their vehicle. This label will be applied by the owner without incurring any cost

How Remedy Component Differs from Recalled Component : The front tire pressure should be 52 psi not 46 psi

Identify How/When Recall Condition was Corrected in Production : The front tire pressure stated on the label was changed on Nov 18, 2021

Recall Schedule :

Description of Recall Schedule : Dealer notification May 30 to June 3
Owner notification June 6 to 10

Planned Dealer Notification Date : MAY 30, 2022 - JUN 03, 2022

Planned Owner Notification Date : JUN 06, 2022 - JUN 10, 2022

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

* NR - Not Reported