OMB Control No.: 2127-0004

Part 573 Safety Recall Report

22V-166

Manufacturer Name: Newmar Corporation

Submission Date: MAR 17, 2022 **NHTSA Recall No.:** 22V-166

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Newmar Corporation

Address: 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone: 574-773-7791

Population:

Number of potentially involved: 58 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2021-2022 Newmar New Aire

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

Descriptive Information: On certain Newmar Class A motorhomes built on Freightliner chassis, a problem with

the upper

nut/bolt connecting the steering column not being torqued down correctly which could result in the nut coming loose and falling off the bolt. This could result in the

loss of steering control and increase the risk of a crash.

New Aire = 13

Production Dates: JAN 15, 2021 - JUL 28, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2021-2022 Newmar Dutch Star

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

Descriptive Information: On certain Newmar Class A motorhomes built on Freightliner chassis, a problem with

the upper

nut/bolt connecting the steering column not being torqued down correctly which could result in the nut coming loose and falling off the bolt. This could result in the

loss of steering control and increase the risk of a crash.

Dutch Star = 45

Production Dates: JAN 15, 2021 - JUL 28, 2021

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Description of Defect:

Description of the Defect: On certain Newmar Class A motorhomes built on Freightliner chassis, a

problem with the upper

nut/bolt connecting the steering column not being torqued down correctly which could result in the nut coming loose and falling off the bolt. This could

result in the loss of steering control and increase the risk of a crash.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: On certain Newmar Class A motorhomes built on Freightliner chassis, a

problem with the upper

nut/bolt connecting the steering column not being torqued down correctly which could result in the nut coming loose and falling off the bolt. This could

result in the loss of steering control and increase the risk of a crash.

Description of the Cause: NR
Identification of Any Warning NR
that can Occur:

Involved Components:

Component Name 1: Steering Column Upper Bolt/Nut

Component Description: Bolt/Nut

Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: Daimler Trucks North America, LLC

Address: PO Box 3849

Portland Oregon 972208

Country: United States

Chronology:

Newmar Corporation is reporting this recall following an initial warranty claim on 03/09/22 that initiated a safety review meeting of the issue. It was determined at the safety review meeting on 3/10/22 a recall should

be issued with the initial 58 units noted in this recall.

Description of Remedy:

Description of Remedy Program : Newmar Corporation will be conducting this recall in its entirety. Units

identified as having a possible steering column issue will have the upper and lower nut/bolt checked for the correct torque and if needed tightened to the correct torque. All repairs will be at no cost to customer. If the customer has had the repair performed before receiving this letter, they may be eligible to receive reimbursement for the cost of obtaining a prenotification remedy. For additional information contact Newmar Service

Department, 355 N. Delaware St, Nappanee, IN 46550

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: On or before 05/16/2022, customer/dealer letters will be sent out.

Planned Dealer Notification Date : MAY 16, 2022 - MAY 16, 2022 Planned Owner Notification Date : MAY 16, 2022 - MAY 16, 2022

* NR - Not Reported