



VOLKSWAGEN DEALER COMMUNICATION

REVISION – Safety Recall 42L8 / Rear Suspension Knuckles

This notice is for:

✓ Dealer Principal	✓ Service Manager	✓ Warranty Administrator
✓ General Manager	✓ Parts Manager	✓ Technicians
✓ Sales Managers	✓ Service Consultant	

Date: June 10, 2022

Revision Summary: On June 10, 2022 a revised 42L8 Safety Recall circular is published with an updated parts table to include an added bonded rubber bushing. The claiming sections, work instructions, and required tools sections have been updated accordingly.

Please see the revised circular for Safety Recall 42L8 that is published in Elsa and ServiceNet for additional information.

IMPORTANT REMINDER: VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS

New Vehicles in Dealer Inventory: It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

Pre-Owned Vehicles in Dealer Inventory: Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Volkswagen Public Relations.