

Part 573 Safety Recall Report

22V-206

Manufacturer Name : Keystone RV Company**Submission Date :** MAR 30, 2022**NHTSA Recall No. :** 22V-206**Manufacturer Recall No. :** 22-429**Manufacturer Information :****Population :**

Manufacturer Name : Keystone RV Company

Number of potentially involved : 35

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Estimated percentage with defect : 100 %

Company phone : 574-535-2100

Vehicle Information :

Vehicle 1 : 2022-2022 Keystone Passport 2704RKWE, 2951BHWE

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : 2704RKWE, 2951BHWE

Production Dates : OCT 21, 2021 - MAR 01, 2022

VIN Range 1 : Begin : 4YDTPPM28NX411333 End : 4YDTPPN22NX414355 ☒ Not sequential**Description of Defect :**

Description of the Defect : It has been decided that vehicles in this population have 3500 pound axles and ST205/75R15D tires and rims rather than the 4400 pound axles and ST225/75R15D tires and rims as specified on the Federal Identification Tag.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Undersized axles, tires, and rims can be overloaded leading to an increased risk of vehicle crash.

Description of the Cause : The incorrect axles and tire wheel combination were installed.

Identification of Any Warning that can Occur : Inspect the Federal Identification Sticker and compare it to the installed axles.

Involved Components :

Component Name 1 : Axle 3500#

Component Description : Axle - 3500# - Straight - Overslung - 85" Hub Face

Component Part Number : 427729

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

3/11/2022 – Report was made during a routine audit that the incorrect axles were installed in production.

3/11/2022 to 3/17/2022 – Investigation opened. All affected units were put on hold and axles was inspected.

A phone initiated inquiry was made to confirm axle sizes on dealer lots.

3/17/2022 – Keystone Safety Committee reviewed the information and concluded that the data reviewed indicated a unanimous vote for a voluntary recall. Investigation called for to determine affected unit range.

3/23/2022 – Investigation concluded and scope completed.

Description of Remedy :

Description of Remedy Program : The remedy is replace the axles and tires/rims with the proper size. Manufacturer Reimbursement Plan on file as of 10/07/2020. General reimbursement plan to be updated every two years. New vehicles are covered under warranty.

How Remedy Component Differs from Recalled Component : The remedy parts are correctly sized for the GVWR.

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : MAY 17, 2022 - MAY 17, 2022

Planned Owner Notification Date : MAY 17, 2022 - MAY 17, 2022

* NR - Not Reported