



KEYSTONE
RV COMPANY

RECREATIONAL VEHICLE
SAFETY RECALL NOTICE

Safety Recall: 22V-208
Safety Advisory: 22-428
May 11, 2022

IMPORTANT SAFETY RECALL

«Owner_name»
«Street»
«Street_2»
«City», «State» «Zip»

This notice applies to your vehicle: «VIN»

Dear «Owner_name»:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model 2022 Alpine, Arcadia, Avalanche, Fuzion, Impact, Passport Fifth Wheels and Travel Trailers. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

Reason for this recall

It has been decided that the vehicles in the recall population have a 50 amp shore power inlet with a #2 Philips lug that may have been improperly stamped, not allowing it to be properly torqued by the installer. Under certain conditions if the lug is not properly torqued to 20 inch pounds, the loose connection can lead to an increased risk of property damage or fire.

What we will do

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to remove the 50 amp shore receptacle on suspect vehicles and torque lugs to 20 inch pounds. If 20 inch pounds cannot be reached, the 50 amp shore receptacle is to be replaced. The service and parts required for this corrective action will be provided at no charge to you.

What we need you to do

Vehicles should be taken to an authorized dealer and the torque inspected on the 50 amp shore receptacle lugs before plugging the unit into shore power. As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately ½ hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

If you have questions

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. Please contact Keystone Customer service if your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you. You may be eligible to receive reimbursement if you paid to have the defect resolved prior to receiving this correspondence. Keystone Customer Service is available toll-free at 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.nhtsa.gov>.) Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your attention and cooperation in this matter.

Sincerely,

KEYSTONE RV COMPANY

cc: National Highway Traffic Safety Administration (NHTSA)

PO Box 2000 – Goshen, IN 46527-2000
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com

