

CAMPAIGN LAUNCH STATUS

N678 SAFETY RECALL - DRIVER SAFETY BELT ELR OPERATION



SAFETY RECALL N678 – DRIVER SAFETY BELT EMERGENCY LOCKING RETRACTOR	
AFFECTED MODELS	2016-2017 Range Rover and Range Rover Sport
VOLUME AFFECTED	USA 14,812 Canada 1,256
REPAIR	The emergency locking retractor in the driver safety belt assembly may not be to specification. Retailers will inspect driver safety belt part numbers and date codes and following instructions in the bulletin, will replace any defective parts.
REPAIR TIME	Between 0.1 and 0.3 hrs + DIDO
CAMPAIGN LAUNCH	Target May 27 th , 2022
Notes	This recall supersedes N333. See Interim Notification Bulletins NAS22.04.008 USA and NAS22.04.009 CAN posted to GRP April 19 th 2022.

