

TOPIC	TYPE	RECALL CODE	QUESTION	ANSWER								
Safety Recall 66N5	Safety Recall	66N5	What vehicles are included in Safety Recall 66N5?	<table border="1"> <thead> <tr> <th>Country</th> <th>Beginning Model Year</th> <th>Ending Model Year</th> <th>Vehicle</th> </tr> </thead> <tbody> <tr> <td>USA</td> <td>2018</td> <td>2022</td> <td>TIGUAN</td> </tr> </tbody> </table>	Country	Beginning Model Year	Ending Model Year	Vehicle	USA	2018	2022	TIGUAN
Country	Beginning Model Year	Ending Model Year	Vehicle									
USA	2018	2022	TIGUAN									
			What is the safety concern for Safety Recall 66N5?	Due to possible poor adhesion of the accessory rear hatch spoiler to the vehicle body, there is a risk of the spoiler coming loose and falling off the vehicle. If the spoiler falls from the vehicle, it can become a hazard on the roadway for other traffic, posing a potential crash and injury risk to others.								
			Are there any precautions I should take because my vehicle is part of Safety Recall 66N5?	If the recall condition is present on the vehicle, customers may notice that the spoiler has become loose or separated from the vehicle hatch. If this happens, customers are advised to contact an authorized Volkswagen dealer to have the issue addressed without delay.								
			What is the repair for Safety Recall 66N5?	Replace accessory rear hatch spoiler.								
			When will the repair for Safety Recall 66N5 be available?	Repairs for this recall have begun. Please contact your authorized Volkswagen dealer without delay to schedule this recall repair. To set up an appointment online, please visit www.vw.com/find-a-dealer .								