

Recall Quarterly Report**22V-238**

Manufacturer Name : Toyota Motor Engineering & Manufacturing
NHTSA Recall No. / MFR Recall No. : 22V-238 /22LA02
Recall Subject : Missing Welds May Cause Shock Absorber to Separate
Owner Notification Beginning Date : JUN 10, 2022
Owner Notification End Date: JUN 10, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 14, 2022	2022-2	4,215	2,135	1	3

This Document Last Updated : JUL 15, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
Recall Population : The total number of products recalled by the manufacturer.
Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.
Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.
Total Removed : Products that have been scrapped, stolen, or exported.