



IKON
XL
Classic
Explorer
Verona LE

Verona
Valencia
Veracruz
Vienna
Villagio

IMPORTANT SAFETY RECALL
Renegade RV Recall Campaign 22V268
February 28,2022
THIS NOTICE APPLIES TO YOUR VEHICLE

Renegade RV
52216 State Road 15
Bristol, IN 46507

February 28, 2022

Attention: **Renegade Owner** _____
This notice pertains to Vin. # _____ **Unit #** _____

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Renegade RV has decided that a defect, which relates to motor vehicle safety, exists in certain 2021 Vienna/Villagio vehicles. Upon receipt of this notice contact your local service center to schedule an appointment to have the remedy performed. Renegade RV will execute this remedy (0.5 labor hours allotted for relay only). The service center is to order the part kit (# 4520068) that Renegade RV will supply at **NO CHARGE** and complete the repair for free.

What is the issue: Possibility for a fire at the 110 VAC load center due to heat from the Dayton/Snyder Electric relay.

What is the safety risk: The possibility of the 110 VAC load center and or the DAYTON/Snyder Electric relay distorting, melting and up to causing a fire.

Identify any warning which can precede or occur: Possibility of smell and/or smoke.

What is the cause: Stranded wire used in a compression style connector causing heat within the relay.

What is the Remedy: **At no cost to the customer**, Renegade will remove jumper wire from Dayton/Snyder Electric relay to main breaker. Move S.J. wire from Dayton/Snyder Electric relay to main breaker. Remove the Dayton/Snyder Electric relay, remove 12 VDC trigger wires from the 110 VAC load center with the relay, cap off 12 VDC wires, using bell connectors, and secure behind load center with zip tie. Add decal by Firefly touch screen indicating **““Don’t use Range, Microwave or Air Conditioning unit unless coach is powered by shore or Generator”** The Dayton/Snyder Electric relay does not allow for the range, microwave, or A/C to operate off the inverter by sensing shore/generator power through the transfer switch.



**IKON
XL
Classic
Explorer
Verona LE**

**Verona
Valencia
Veracruz
Vienna
Villagio**

Removal of the relay will allow the range, microwave, and A/C to operate on the inverter. Customer to be made aware of load management with this change.

If you have incurred expense to remedy this issue prior to the date of this notice, you may have the opportunity to obtain reimbursement for that expense. For details, contact us at the number or email address provided.

warranty@renegaderv.com

Jaxon Prill-574-966-0166

John Wood-574-966-0193

If you believe that Renegade RV has failed, or is unable to remedy this defect without charge and within a reasonable amount of time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E. Washington DC 20590; or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Renegade RV is committed to providing the best products that enable our customers to enjoy a mobile lifestyle and we apologize for any inconvenience this may cause.

Best regards,

Kirk Manring
Customer Service Manager
Renegade Mfg.



Office: 574-966-0160

kmanring@renegaderv.com