



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

May 10, 2022

Mr. Gerard Hones
Mack Trucks, Inc.
7900 National Service Road
Greensboro, NC 27409

NEF-107MR
22V-295

Subject: Insufficient Air Volume in Brake System

Dear Mr. Hones:

This letter serves to acknowledge Mack Trucks, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
MACK/GRANITE (GR)/2022

Mfr's Report Date: May 3, 2022

NHTSA Campaign Number: 22V-295

Components:
SERVICE BRAKES, AIR

Potential Number of Units Affected: 14

Problem Description:

Mack Trucks, Inc. (Mack) is recalling certain 2022 Granite trucks. The air tanks have an insufficient volume of air for the brake system. As such, these vehicles fail to comply with the requirements of the Federal Motor Vehicle Safety Standard number 121, "Air Brake Systems."

Consequence:

Insufficient air volume can reduce braking performance and increase the risk of a crash.

Remedy:

Dealers will install new air tanks, free of charge. Owner notification letters are expected to be mailed on July 1, 2022. Owners may contact Mack's customer service at 1-800-866-1177. Mack's number for this recall is SCC 0435.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Per the requirements of 573.6(c)(2)(iv), please provide the supplier name, contact information, address and country of origin (if known) for the air tank. If your company manufactured the component itself, then please state so in 573.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Mack Trucks, Inc.'s contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement