

Part 573 Safety Recall Report

22V-300

Manufacturer Name : Thor Motor Coach**Submission Date :** JUN 09, 2022**NHTSA Recall No. :** 22V-300**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Thor Motor Coach

Number of potentially involved : 3,374

Address : PO Box 1486

Estimated percentage with defect : 100 %

701 County Road 15 Elkhart IN 46515

Company phone : 877-500-1020

Vehicle Information :

Vehicle 1 : 2022-2022 Thor Motor Coach Sequence

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : GAS

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JUL 01, 2021 - FEB 04, 2022

VIN Range 1 : Begin : 3C6MRVUG0ME541601 End : 3C6MRVUGXME587890 ☒ Not sequential

Vehicle 2 : 2022-2022 Thor Motor Coach Tranquility

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : DIESEL

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JUL 13, 2021 - FEB 04, 2022

VIN Range 1 : Begin : W1X4EBVY0LT034357 End : W1X4EBVYXMT065469 ☒ Not sequential

Vehicle 3 : 2022-2022 Thor Motor Coach Rize

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : GAS

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JUL 01, 2021 - FEB 07, 2022

VIN Range 1 : Begin : 3C6ERVBG4ME506194 End : 3C6LRVBGXME573437 ☒ Not sequential

Vehicle 4 : 2022-2022 Thor Motor Coach Scope

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : GAS

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JUL 13, 2021 - FEB 04, 2022

VIN Range 1 : Begin : 3C6ERVBG6ME506195 End : 3C6LRVBGXME577889 ☒ Not sequential

Vehicle 5 : 2022-2022 Thor Motor Coach Tellaro

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : GAS

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JUL 14, 2021 - FEB 01, 2022

VIN Range 1 : Begin : 3C6MRVUG0ME541548 End : 3C6MRVUGXME587873 ☒ Not sequential

Vehicle 6 : 2022-2022 Thor Motor Coach Sanctuary

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : DIESEL

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JUL 13, 2021 - FEB 07, 2022

VIN Range 1 : Begin : W1X4EBVY0LT035590 End : W1X4EBVYXMT072986 ☒ Not sequential

Vehicle 7 : 2022-2022 Thor Motor Coach Synergy

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : GAS

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JAN 20, 2022 - JAN 20, 2022

VIN Range 1 : Begin : W1X4EBHY2MT079104 End : W1X4EBHY2MT079104 ☐ Not sequential

Vehicle 8 : 2022-2022 Thor Motor Coach Four Winds

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : DIESEL

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JUL 01, 2021 - APR 26, 2022

VIN Range 1 : Begin : 1FDXE4FN0NDC16985 End : 1HA6GUC79MN012335 ☒ Not sequential

Vehicle 9 : 2022-2022 Thor Motor Coach Delano

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : DIESEL

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JUL 20, 2021 - MAR 04, 2022

VIN Range 1 : Begin : W1X8E33Y0LN129564 End : W1X8E33YXMN154036 ☒ Not sequential

Vehicle 10 : 2022-2023 Thor Motor Coach Gemini

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : GAS

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JUL 21, 2021 - MAR 09, 2022

VIN Range 1 : Begin : 1FDRU8PG0MKA34037 End : 1FDRU8PGXMKA93127 ☒ Not sequential

Vehicle 11 : 2022-2022 Thor Motor Coach Quantum

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : DIESEL

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JUL 15, 2021 - FEB 17, 2022

VIN Range 1 : Begin : 1FDXE4FN0NDC28635 End : W1X8E33Y5LN130676 ☒ Not sequential

Vehicle 12 : 2022-2023 Thor Motor Coach Tiburon

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : DIESEL

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JUL 26, 2021 - MAR 01, 2022

VIN Range 1 : Begin : W1X8E33Y0LN128656 End : W1X8E33YXMN153744 ☒ Not sequential

Vehicle 13 : 2022-2022 Thor Motor Coach Magnitude

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : DEC 03, 2021 - MAR 15, 2022

VIN Range 1 : Begin : 1FDXE4FN0NDC20969 End : 1FDXE4FNXNDC36855 ☒ Not sequential

Vehicle 14 : 2022-2022 Thor Motor Coach Geneva
 Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES
 Body Style : OTHER
 Power Train : GAS

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : NOV 01, 2021 - NOV 01, 2021

VIN Range 1 : Begin : 1FDXE4FN3NDC21002 End : 1FDXE4FN3NDC21002 ☐ Not sequential

Vehicle 15 : 2022-2022 Thor Motor Coach Compass
 Vehicle Type : LIGHT VEHICLES
 Body Style : VAN
 Power Train : GAS

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : JUL 23, 2021 - FEB 28, 2022

VIN Range 1 : Begin : 1FDRU8PG0MKA34040 End : 1FDRU8PGXMKA96609 ☒ Not sequential

Vehicle 16 : 2022-2022 Thor Motor Coach Chateau
 Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES
 Body Style : OTHER
 Power Train : GAS

Descriptive Information : Notice from vendor of defective Quick Connect Brass fitting.

Production Dates : OCT 01, 2021 - MAR 11, 2022

VIN Range 1 : Begin : 1FDXE4FN0NDC26738 End : 1HA6GUC7XMN009234 ☒ Not sequential

Description of Defect :

Description of the Defect : These vehicles may be equipped with quick disconnect couplers supplied to Thor Motor Coach by Enerco Group, Inc. Enerco has issued a recall for these fittings.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The defective fittings may crack and leak, causing a risk of a fire.

Description of the Cause : According to Enerco, some of the brass components may have porosity, contamination, and carbon.

Identification of Any Warning that can Occur : The crack may be visible.

Involved Components :

Component Name 1 : Propane quick disconnect

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Enerco Group, Inc.

Address : 4650 W. 160th Street
Cleveland Ohio 44135

Country : United States

Chronology :

Provide the chronology of events leading up to the defect decision or test data for the noncompliance decision:

4/20/2022 – TMC is notified by Enerco of their recall. TMC begins investigation into usage of this part.

4/21/2022 – Enerco provides information regarding supplied product.

4/25/2022 – TMC determines that fittings are being used and continues to determine the scope of the units involved.

5/3/2022 – TMC hold safety committee meeting and votes to issue a recall.

5/13/2022 - TMC has had zero claims or incidents in the field for this issue.

Description of Remedy :

Description of Remedy Program : Replace the fittings

How Remedy Component Differs from Recalled Component : Proper quality brass

Identify How/When Recall Condition was Corrected in Production : Supplier corrected

Recall Schedule :

Description of Recall Schedule : TMC will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : JUL 04, 2022 - JUL 04, 2022

Planned Owner Notification Date : JUL 04, 2022 - JUL 04, 2022

* NR - Not Reported