

# Part 573 Safety Recall Report

## 22V-305

**Manufacturer Name :** Heartland Recreational Vehicles, LLC**Submission Date :** MAY 06, 2022**NHTSA Recall No. :** 22V-305**Manufacturer Recall No. :** TBD**Manufacturer Information :****Population :****Manufacturer Name :** Heartland Recreational Vehicles, LLC**Number of potentially involved :** 69**Address :** 1001 All Pro Drive**Estimated percentage with defect :** 100 %**Elkhart IN 46514****Company phone :** 8772628032**Vehicle Information :****Vehicle 1 :** 2022-2022 Heartland Sundance**Vehicle Type :** TRAILERS**Body Style :** OTHER**Power Train :** NR**Descriptive Information :** The population was determined from when the line employee did not install a 12v mini breaker cover to when it was discovered.**Production Dates :** MAR 31, 2022 - APR 14, 2022**VIN Range 1 : Begin :** 5SFSB3624NE509481 **End :** 5SFSB3622NE509656 ☒ Not sequential**Description of Defect :****Description of the Defect :** The required 12v mini breaker cover for the slide-out was not installed during production. This has led to exposed studs that could cause arching.**FMVSS 1 :** NR**FMVSS 2 :** NR**Description of the Safety Risk :** Exposed studs on the mini breaker can be touched by the aluminum ducting in the area. This could cause arching and lead to an increased risk of fire and personal injury.**Description of the Cause :** The rubber cover was not installed during production to protect the studs on the 12v mini breaker.**Identification of Any Warning** There will be no red rubber cover on the mini breaker for the slide-out room

that can Occur : located behind the converter.

### Involved Components :

Component Name 1 : Mini breaker rubber boot

Component Description : Mini breaker rubber boot

Component Part Number : 11131: Boot - VTE-464NOV02 - Rubber

### Supplier Identification :

#### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

### Chronology :

4/26/22 received an email from production about missing covers on mini breakers. 4/27/22 - 4/29/22 Ran warranty claims and determining scope and range. 4/29/22 - called safety committee meeting. 4/30/22 voted to recall. We have had zero warranty claims and zero personal injuries or property damage.

### Description of Remedy :

Description of Remedy Program : Heartland will have an authorized dealer or repair center inspect the 12-volt mini breaker for the slide-out. If found missing, the dealer will cap the mini breaker with the proper cap. This repair should take no more than 15 minutes to complete. This defect will be corrected at no expense to you, the owner. All Reimbursements will be covered by Heartland's general reimbursement plan.

How Remedy Component Differs The mini breaker will have a red rubber boot VTEE-464NOV02 installed.

from Recalled Component :

Identify How/When Recall Condition was Corrected in Production : Production began re-installing the cap once the omission was found.

### Recall Schedule :

Description of Recall Schedule : Heartland will begin notifying owners/dealers once letters are approved

Planned Dealer Notification Date : JUL 01, 2022 - JUL 01, 2022

Planned Owner Notification Date : JUL 01, 2022 - JUL 01, 2022

\* NR - Not Reported