

Part 573 Safety Recall Report

22V-325

Manufacturer Name : Beta USA**Submission Date :** MAY 11, 2022**NHTSA Recall No. :** 22V-325**Manufacturer Recall No. :** R-2022-1**Manufacturer Information :**

Manufacturer Name : Beta USA

Address : PO box 4099

Paso Robles CA 93447

Company phone : 805-226-4035

Population :

Number of potentially involved : 97

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2022-2022 Beta 350 RR-S

Vehicle Type : MOTORCYCLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : We had a shipment of bikes show with the incorrect front brake hose installed. We notified the factory and were able to look at production build sheets and noticed two runs where built with the incorrect front brake hose part number listed. There was 97 units affected with a combination of 2022 350 RR-S, 2022 390 RR-S, 2022 430 RR-S, and 2022 500 RR-S.

Production Dates : DEC 03, 2021 - DEC 28, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 2 : 2022-2022 Beta 390 RR-S

Vehicle Type : MOTORCYCLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : We had a shipment of bikes show with the incorrect front brake hose installed. We notified the factory and were able to look at production build sheets and noticed two runs where built with the incorrect front brake hose part number listed. There was 97 units affected with a combination of 2022 350 RR-S, 2022 390 RR-S, 2022 430 RR-S, and 2022 500 RR-S.

Production Dates : DEC 03, 2021 - DEC 28, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 3 : 2022-2022 Beta 430 RR-S

Vehicle Type : MOTORCYCLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : We had a shipment of bikes show with the incorrect front brake hose installed. We notified the factory and were able to look at production build sheets and noticed two runs where built with the incorrect front brake hose part number listed. There was 97 units affected with a combination of 2022 350 RR-S, 2022 390 RR-S, 2022 430 RR-S, and 2022 500 RR-S.

Production Dates : DEC 03, 2021 - DEC 28, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 4 : 2022-2022 Beta 500 RR-S

Vehicle Type : MOTORCYCLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : We had a shipment of bikes show with the incorrect front brake hose installed. We notified the factory and were able to look at production build sheets and noticed two runs where built with the incorrect front brake hose part number listed. There was 97 units affected with a combination of 2022 350 RR-S, 2022 390 RR-S, 2022 430 RR-S, and 2022 500 RR-S.

Production Dates : DEC 03, 2021 - DEC 28, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : The factory installed the incorrect front brake hose during production.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Having the incorrect front brake hose installed can lead to the hose not getting enough free play and possibly getting caught onto the speedometer/dash board. This can cause damage to the speedometer/dash board, and possibly disconnect the front brake hose which could lead to injury or harm.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Front Brake Hose

Component Description : Front Brake Hose

Component Part Number : 037-360020-000

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

3/17/2022: Dealer notified our service dept stating bike they received came with incorrect front brake hose.

3/18/2022: Check units at our facility and confirmed they came with incorrect front brake hose. Notified the Factory with the VIN's and Invoice #'s to help them locate the production run.

3/22/2022: Factory located the production runs that had the incorrect front brake hose installed notified us with a list for us to notify the dealers & customers.

3/28/2022: Received correct front brake hoses to send to dealers.

Description of Remedy :

Description of Remedy Program : Beta will notify the owners and replace the front brake hose free of charge. Our factory has sent all the replacements to our facility to send to dealers.

How Remedy Component Differs from Recalled Component : You can tell by the part number listed on the brake hose it will read 29.09108.000 appose to the recalled # 37.36.002.00.00. You can also tell by how the front brake hose connects to the Master Cylinder on the handler bars. The remedy component has a slight bend to the hose where it installs to the master cylinder as the recalled will go straight directly in.

Identify How/When Recall Condition was Corrected in Production : We notified the factory on 3/18/2021 and they were able to locate the productions that had the incorrect brake hose installed and replaced them all.

Recall Schedule :

Description of Recall Schedule : Dealer will be emailed from constant contact, and a recall bulletin will be

posted to our dealer website. For the customers we will be sending out a letter to their address.

Planned Dealer Notification Date : MAY 16, 2022 - MAY 16, 2022

Planned Owner Notification Date : MAY 17, 2022 - MAY 20, 2022

* NR - Not Reported